

MAY 25 1972

J. C. Kippel, Chief, Reactor Testing & Operations Br.  
 Directorate of Regulatory Operations, HQ

RO INSPECTION REPORT NO. 50-219/72-03  
 JERSEY CENTRAL POWER & LIGHT COMPANY  
 OYSTER CREEK - BWR

The subject inspection report is forwarded for your information.

Our concerns, as well as the details relating to the labor problems and the cracks found on the seat bushing of two safety valves at OC-1, were previously advanced to your office via Inquiry Reports Nos. 50-219/72-09 and 10. The labor problems were subsequently resolved and the plant was shut down for the refueling outage on May 1, 1972. With regard to the safety valves, we understand that all valves (total of 16) have been removed and returned to the manufacturer for inspection and resetting.

Regarding the occurrence of de-inerting and re-inerting the containment atmosphere during operation and within a 24 hour period, this matter, as well as the Tech Spec requirements, were reviewed with Mr. James P. O'Reilly, Director, Region I, and our position is that the intent of the Technical Specifications was not violated.

R. T. Carlson  
 Chief, Reactor Operations Branch

Enclosure:  
 Subject Inspection Report

cc: E. Minogua, RS (3)  
 E. V. Boyd, L (2)  
 E. C. DeYoung, L (2)D  
 D. J. Shevchelt, L (3)  
 H. A. Denton, L (2)  
 Office of Operations Evaluation, RO  
 Asst. Director for Procedures, RO  
 R. H. Engelken, RO  
 RO Files

18 Central Files

OFFICE ▶	RO				
SURNAME ▶	Spessard: smg				
DATE ▶	5/24/72				