

631 Park Avenue
King of Prussia, Pennsylvania 19406

FEB 6 1974

H. D. Thornburg, Chief
FS&EB
RO:HQ

RO INSPECTION REPORT NO. 50-219/74-01
JERSEY CENTRAL POWER AND LIGHT COMPANY
OYSTER CREEK - BWR

The subject inspection report is forwarded for action. A documentation letter has been issued to the licensee by this office.

Action is requested on the following matters:

1. Either an interim or full term Environmental Technical Specification for Oyster Creek be issued in view of the prolonged delays and slippage concerning the full term operating license.
2. DL establish a schedule coordinated with the licensee, initiating a JCP&L course of action designed to mitigate and correct the ecological consequences of:
 - a) fish mortalities resulting from winter shutdown and to be implemented by the fall of 1974;
 - b) erosion of the banks along the influent canal and resultant silting problems. (The effluent canal is also subject to erosion.)

If you have any questions, please contact us.

Eldon J. Brunner, Chief
Reactor Operations Branch

A/638

OFFICE ▶	RO:I;kmf	<i>ABD</i>			
SURNAME ▶	Capton	Brunner			<i>PS</i>
DATE ▶	<i>2/6</i>	<i>2/6</i>			<i>2/7/74</i>

Form AEC-518 (Rev. 9-53) AECM 0240

9604180132 960213
PDR FOIA
DEKOK95-258 PDR

631 Park Avenue
King of Prussia, Pennsylvania 19406

FEB 6 1974

H. D. Thoraburg, Chief
FS&EB
RO:HQ

RO INSPECTION REPORT NO. 50-219/74-01
JERSEY CENTRAL POWER AND LIGHT COMPANY
OYSTER CREEK - BWR

The subject inspection report is forwarded for action. A documentation letter has been issued to the licensee by this office.

Action is requested on the following matters:

1. Either an interim or full term Environmental Technical Specification for Oyster Creek be issued in view of the prolonged delays and slippage concerning the full term operating license.
2. DL establish a schedule coordinated with the licensee, initiating a JCP&L course of action designed to mitigate and correct the ecological consequences of:
 - a) fish mortalities resulting from winter shutdown and to be implemented by the fall of 1974;
 - b) erosion of the banks along the influent canal and resultant silting problems. (The effluent canal is also subject to erosion.)

If you have any questions, please contact us.

Elton J. Brunner, Chief
Reactor Operations Branch

B1639

OFFICE ▶	RO:I;kmf	ASB for			PS	
SURNAME ▶	Capton	Brunner			Storj	
DATE ▶	2/6	2/6			2/7/74	