



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

Yellow
V-2 B2

JUN 13 1974

MEMO TO DOCKET FILE 50-219

TELEPHONE CALL TO JOHN RIESLAND, DIRECTORATE OF LICENSING, PROJECT MANAGER,
OYSTER CREEK

I called Mr. John Riesland on June 5, 1974 to discuss the matter of the instrument penetration leak in the reactor vessel bottom head. Mr. Riesland was briefed on the status and progress being made by the licensee. It was stated to Mr. Riesland that the licensee had currently not defined the cause or the exact location of the leak. It was stated that the licensee's current schedule for repair and returning the reactor to operations was June 10, 1974. The areas of responsibility between Licensing and Directorate of Regulatory Operations was discussed. Mr. Riesland stated that he had no problem with the action being taken by Regulatory Operations and stated that if RO required any action on the part of DL that we should contact DL. Mr. Riesland agreed that RO should continue to handle the follow-up on this matter. Mr. Riesland further stated that he had contacted the DL Technical Support Group for the purposes of alerting them to the possibility of their involvement.

D. L. Capton

D. L. Capton
Senior Reactor Inspector
Facilities Operation Branch

B/S12