




Public Service

Public Service
Company of Colorado
P.O. Box 840
Denver, CO 80201 - 0840
(303) 571 - 7511

February 6, 1985
Fort St. Vrain
Unit No. 1
P-85049

Regional Administrator
Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Attention: Mr. E. H. Johnson



Docket 50-267

SUBJECT: Failures to Scram - Control Rod
Drive and Orifice Assemblies

- REFERENCES:
- 1) NRC Letter, R. D. Martin to
O. R. Lee, 1/17/85 (G-85024)
 - 2) PSC Letter, O. R. Lee to
E. H. Johnson, 1/28/85
(P-85030)
 - 3) PSC Letter, D. W. Warembourg to
E. H. Johnson, 1/31/85
(P-85037)

Dear Mr. Johnson:

Enclosed are the twenty remaining copies of Public Service Company's
Engineering Report #EE-12-0010 entitled, "Failures to Scram - Control
Rod Drive and Orifice Assemblies." The original copies were
submitted via Reference 3.

If you have any questions, please contact Mr. M. H. Holmes at (303)
571-8409.

Very truly yours,

D. W. Warembourg
D. W. Warembourg
Manager, Nuclear
Engineering Division

8502250704 850206
PDR ADDCK 05000267
P PDR

DWW/RLC/ksc

Attachments

H005
RETURN ORIGINAL
TO RIV
1/0