

ENCLOSURE 1

NOTICE OF VIOLATION

Tennessee Valley Authority
Bellefonte Unit 1

Docket No. 50-438
License No. CPPR-122

The following violations were identified during an inspection conducted on February 7-11, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50.54(a)(1) requires the licensee to implement the quality assurance program described in TVA Topical Report TVA-TR-75-1A. Section 17.2.5 of the report requires that activities affecting safety-related functions be conducted in compliance with the Office of Power procedures. Procedure BLA 16.1, Identification of Conditions Adverse to Quality and Corrective Actions, requires documentation of conditions adverse to quality within three working days of identification of the condition and specifies the manner of documentation.

Contrary to the above, by March 2, 1984, a condition adverse to quality, froth on the station batteries, had not been documented in accordance with BLA 16.1 although it had been identified in September 1981.

This is a Severity Level V Violation (Supplement 2).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: **MAR 22 1984**

8411080350 841031
PDR ADOCK 05000438
G PDR