

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Prairie Island Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 0 1 6	PAGE (3) 1 OF 0 2
--	--	----------------------

TITLE (4)  
Two pressurizer pressure instruments found out of calibration.

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 9	2 8	8 4	8 4	0 0 2	0 0	1 0	2 9	8 4	Prairie Island Unit 1		0 5 0 0 0 2 8 2
											0 5 0 0 0

OPERATING MODE (9) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)											
POWER LEVEL (10) 0 0 1 0	20.402(b)			20.406(a)(1)(i)			20.406(a)(1)(ii)			20.406(a)(1)(iii)		
	20.406(a)(1)(iv)			20.406(a)(1)(v)			20.406(a)(1)(vi)			20.406(a)(1)(vii)		
	20.406(a)(1)(viii)			20.406(a)(1)(ix)			20.406(a)(1)(x)			20.406(a)(1)(xi)		
	20.406(a)(1)(xii)			20.406(a)(1)(xiii)			20.406(a)(1)(xiv)			20.406(a)(1)(xv)		
	20.406(a)(1)(xvi)			20.406(a)(1)(xvii)			20.406(a)(1)(xviii)			20.406(a)(1)(xix)		
			50.38(a)(1)			50.38(a)(2)			50.73(a)(2)(iv)			
			50.73(a)(2)(i)			50.73(a)(2)(ii)			50.73(a)(2)(v)			
			50.73(a)(2)(iii)			50.73(a)(2)(vi)			50.73(a)(2)(vii)			
			50.73(a)(2)(viii)			50.73(a)(2)(ix)			50.73(a)(2)(viii)(A)			
			50.73(a)(2)(x)			50.73(a)(2)(xi)			50.73(a)(2)(viii)(B)			
			50.73(a)(2)(xii)			50.73(a)(2)(xiii)			50.73(a)(2)(ix)			
									73.71(b)			
									73.71(c)			
									OTHER (Specify in Abstract below and in Text, NRC Form 365A)			

LICENSEE CONTACT FOR THIS LER (12)									
NAME Arne A. Hunstad, Staff Engineer							TELEPHONE NUMBER		
							AREA CODE 6 1 2 3 8 8 - 1 1 2 1		

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	

SUPPLEMENTAL REPORT EXPECTED (14)							EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)									1	1	2 1 8 4
<input type="checkbox"/> NO											

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During calibration of pressurizer transmitters at Unit 2 refueling, two transmitters were found out of spec.

Unit 1 transmitters are being checked. A supplemental report will be submitted.

IE22 111

8411120127 841029  
PDR ADOCK 05000306  
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Prairie Island Unit 2	DOCKET NUMBER (2)  0   5   0   0   0   3   0   6	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8   4	-   0   0   2	-   0   0	0   2	OF 0   2

TEXT (If more space is required, use additional NRC Form 365A's) (17)

During calibration of pressurizer transmitters at Unit 2 refueling, two transmitters were found out of spec.

Unit 1 transmitters are being checked. A supplemental report will be submitted.



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5530

October 29, 1984

U S Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-282 License No. DPR-42  
50-306 DPR-60

Two Pressurizer Pressure Instruments Found  
Out of Calibration

The License Event Report for this occurrence is attached.

This event was reported via Emergency Notification System per 10 CFR Part 72  
on September 28, 1984.

*for* Eugene Eckholt  
David Musolf  
Manager - Nuclear Support Services

DMM/EFE/dab

c: Regional Administrator-III, NRC  
NRR Project Manager, NRC  
Resident Inspector, NRC  
MPCA  
Attn: J W Ferman

Attachment

*JE22*  
*1/1*