

## CONFIRMATORY ACTION LETTER

## NUCLEAR REGULATORY COMMISSION

olke

REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

JUL 0 6 1984

Docket No. 50-483

Union Electric Company ATTN: Mr. Donald F. Schnell Vice President - Nuclear Post Office Box 149 - Mail Code 400 St. Louis, MO 63166

Gentlemen:

This refers to a 10 CFR 50.72 reportable event which occurred at 1510 CDT on July 4, 1984. Control room ventilation and containment purge isolation signals were initiated due to a loss of power to three process radiation monitors. Further investigation by your staff revealed manually opened, rather than tripped, power supply breakers in the 120V distribution panel which supplies the radiation monitors.

Based on discussions between you and Mr. C. E. Norelius of my staff, it is our understanding that prior to the Plant Manager's approval to take the reactor critical, you will: (1) conduct a thorough investigation of this event to determine the most probable causes; and (2) provide for NRC review and acceptance, the results of your investigation and corrective actions taken to prevent recurrence.

Please let us know immediately if your understanding differs from that set forth above.

Sincerely,

James G. Keppler Regional Administrator

cc: W. H. Weber, Manager, Nuclear Construction

S. E. Miltenberger, Plant Manager

R. L. Powers, Assistant Manager

Quality Assurance

DMB/Document Control Desk (RIDS)

Resident Inspector, RIII

J. Axelrad, IE

B. Youngblood, NRR

J. Hind, RIII

Region IV

K. Drey

Chris R. Rogers, P.E. Utility Division, Missouri

Public Service Commission

FACILITY/ I IC. II L.

NOTIFICATION

DIVISION OF THEFTE, TS & RESIDENT PROGRAMS

CALLAWAY

TELECON FROM SRI

DATE 06/05/817

Region II Duelly Report

...

FOLLOWUP PER MC 25411. EVENTS APPEAR TO HAVE BEEN CAUSED BY INADVERTERY ACTIONS OF INSTRUMENT AND CONTROL TECHNICIANS AND CONTROL HOOM OPERATORS. THE SENIOR RESIDENT INSPECTOR IS REVIEWING THE EVENTS AND IS FOLLOWING THE LICENSEE'S CORRECTIVE DAMAGE); THREE INSTANCES WHICH INITIATED SPURIOUS LEFTY INJECTION SYSTEM ACTUATION SIGNALS; AND AN INCORRECT VALVE LINEUP IN THE ESW SYSTEM DURING RESTORATION FROM THE SAFETY INJECTION SIGNAL WHICH ALLOWED SERVICE UNTER DUBLING THE PERIOD OF 6/11-8/84, THE FOLLOWING UNPLANNED EVENTS TOOK PLACE AT THE CALLAWAY PLANT UNITLE LICENSEE WAS PERFORMING SURVEILLANCE TESTS IN PREPARATION FOR FUEL LOADS. UNINTENTIONAL CLOSING OF THE RHR PUMPS IN OPERATION (FUMPS WITH PUMPS IN OPERATION (FUMPS WERE IMMEDIATELY TRIPPED WITH NO APPARENT TO BE TRANSFERRED FROM THE COOLING TOWER BASIN TO THE

## Report to operations center

DATE OF EVENT - 07/04/84 TIME OF EVENT - 1610
DATE OF NOTIFICATION - 07/04/84 TIME OF NOTIFICATION - 1858

FACILITY NAME - CALLAWAY 1
TYPE OF FACILITY - POWER REACTOR

REGION - 3

LICENSES EVENT CLASSIFICATION - 10 OFR 50.72 REPORTABLE EVENT, NON EMERGENCY CATEGORIES OF EVENT - ESF ACTUATION LUSS OF POWER

CAUSE OF FAILURE - UNKNOWN

BADICACTIVE RELEASE? NO

EVENT DESCRIPTION -

AT 1610 RECEIVED CONTROL ROOM VENTILATION AND CONTAINMENT PURGE ISOLATION \$10 NALS. FOUND TO BE DUE TO OPEN POWER SUPPLY BREAKERS ON 3 PROCESS MONITORS; ALL FED FROM A SINGLE 120V DIST PANEL. REASON FOR OPEN BREAKERS IS UNKNOWN. THE SE BREAKERS APPEAR TO BE OPENED, NOT TRIPPED. ESFAS RESET, ISOLATION SIGNALS CLEARED AND INCREASED SECURITY PATROLS IN ROOM WITH BREAKERS.

ACTION TAKEN BY HDO/RDO - REG 3, D. DANIELSON PERSON NOTIFYING NRC - R. LAMB PERSON ENTERING REPORT - BAILEY 9. M

DATEY REFERENCE

TACT: TIT/LICENSEE

HOTIFICATION

ITEM OF EVENT

07/06/84

RECEGNAL ACTION

DIVI-100 OF REACTOR PROJECTS (CONTINUED)

CALLAURY

TELECON FROM HU DUTY OFFICEP ON 7/4/84 AT 1510 COT ON 7/4/84. CONTROL ROOM VENTILATION / DD CONTAINMENT PURGE ISOLATION SIGNALS WERE INTITATED DUE TO A LOSS OF POWER TO THREE PROCESS RADIATION MONITORS. FURTHER INVESTIGATION BY THE PLANT STAFF. REVEALED MANUALLY GPENED. RATHER THAN TRIPPED. POWER SUPPLY BREAKERS IN THE 120 V DISTRIBUTION PANEL UNICH SUPPLIES THE RADIATION MONITORS. THE LICENSEL IS INVESTIGATING.

A RITI SAFEGUARDS
INSPECTOR WAS
DISPATCHED TO THE
PLANT TO FOLLOW THE
LICENSEE\*S
INVESTIGATION.

July 4 (LER 84-11) This refers to a 10 CFR 50.72 reportable event which occurred at 1510 CDT on July 4, 1984. Control room ventilation and containment purge isolation signals were initiated due to a loss of power to three process radiation monitors. Further investigation by your staff revealed manually opened, rather than tripped, power supply breakers in the 120V distribution panel which supplies the radiation monitors.

Based on discussions between you and Mr. C. E. Norelius of my staff, it is our understanding that prior to the Plant Manager's approval to take the reactor critical, you will:

(1) conduct a thorough investigation of this event to determine the most probable causes; and (2) provide for NRC review and acceptance, the results of your investigation and corrective actions taken to prevent recurrence.

CAL issued.

July 5

Security Event

(LER 84-09)

July 5

Security Event

(LER 84-08)

THE DE MOTIFICATION I I THE PARTY THE PARTY	1:0118 EDT mic mesion: III mate: 71	4.84
PACILITY ON ONCUMIZATION: Callaway	The same of the sa	D WET EAL BACK ROMETE:
प्रसाम तारक्षामायम् ।	The state of the s	
8. SO.72 (NON-EMERGENCY)		
2. UNPLANNED RELEASE		40.7
3. NOTIFICATION OF UNUSUAL EVENT		
4. ALERT		
S. SITE AND DERENCT		
6. ENERAL EMERGENCY		
7. TRANSPORTATION EVENT		
B. PHYSICAL SECURITY/SAFE GUARDS	eren valu – valo beginning valo	
9. DTHER	•	
AZA A L		
		*
PO-IR ALACTOR EVENT		
POWER PRIOR TO EVENT?	POWER AT TIME OF REMORTS	MESIDENT INFORMED:
	THITIATING SIDUALY	
SAFETY INJECTION OF ECCS?	INITIATING SIDUALT	
ESF ACTUATION		
LED ACTION STATEMENTS		- L
eye for the Righ 's	man lighting (4m	,
	de grantett infrastigat	en coases.
	/	
at 1610 EDI receive	d centrement 100	m restuale
isolation signal	and a containing	rest purge
istitum signal	. Upon investigat	in Lucial
the had list so	wer to 3 rod n	meters.
Intrestigation nene	aled 120 V dieter	eters!
pained dad all	breakers orlying	
<u> </u>		,
The breakers were !	reset and securete	is in slace
RADIGACTIVE RELEASES? (QUANTIFY):	V	/
Fig. 12 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	•	
DTHER MAJOR PROBLEMS?		
PLANNED ACTIONS/PRESS RELEASESS		
PLANNED ACTIONS/PRESS RELEASES?		
	STATE(S)	I DCAL

PLEASE CALL BACK WITH ANY CHANGES OF ADDITIONAL INFORMATION

- Callainy to notify THE FRI. -Church to Call Small . Schnell ... - CAL for them to do authorizing under CLASSIFICATIONI FACILITYS RANCHO SECO REGION: 5 DATE OF EVENT: 07/04/84 NOTIFIED NRCI A Manit done one part few day S. WHICHARD DATE NOTIFIED: 07/04/84 ENTERED REPORTI BAILEY TIME OF EVENT: 1229 ET TIME NOTIFIED: 1229 ET A Call - Calling for Computer - 10 illaho CATEGORYI UPDATE-Stationed at Buchen CAUSEI SO TUBE LEAK & Friger Cuting from Bus HOO/ROO ACTION: REG 5. A. JOHNSON. DESCRIPTION CALLED LICENSEE FOR PLANT STATUST 206F . 225 PSIG IN REACTOR COOLANT SYSTEM. BOING TO WET LAY UP IN BOTH SO. CLASSIFICATION; 10 CFR 50.72 REPORTABLE EVENT. NON EMERGENCY FACILITYI CALLAWAY 1 REGION: 3 DATE OF EVENT: 07/04/84 Storm didn't couse liverter NOTIFIED NRCI R. LAMB DATE NOTIFIED: 07/04/84 ENTERED REPORT! BAILEY TIME OF EVENT: 1610 ET TIME NOTIFIED: 1858 ET CATEGORYI ESF ACTUATION-LOSS OF POWER Justijation on had anyone been around CAUSE ! UNKNOWN HOO/ROO ACTION: REG 3. D. DANIELSON 1510 LUCAL. DESCRIPTION: AT 1610 RECEIVED CONTROL ROOM VENTILATION AND CONTAINMENT PURGE A Manually opened - Digunted suplayee ISOLATION SIGNALS. FOUND TO BE DUE TO OPEN POWER SUPPLY BREAKERS ON 3 PROCESS MONITORS! ALL FED FROM A SINGLE 120V DIST PANEL. REASON FOR OPEN BREAKERS IS UNKNOWN. THESE BREAKERS APPEAR TO BE having to work on 4 of you OPENED. NOT TRIPPED. ESFAS RESET. ISOLATION SIGNALS CLEARED AND INCREASED SECURITY PATROLS IN ROOM WITH BREAKERS. Did other line up + sumellance to see CLASSIFICATIONI PHYSICAL SECURITY/SAFEGUARDS other problems - Result Seen FACILITY CALLAWAY 1 REGION: 3 DATE OF EVENT! 07/04/84 to see who was there NOTIFIED NRCI R. LAMB DATE NOTIFIED: 07/04/84 ENTERED REPORT | BAILEY Adviseremant - Hoppy 4 mof Dig UE TIME OF EVENTI 1948 ET TIME NOTIFIED: 2023 ET CATEGORYI SECURITY-A Not sitelle jand act - some CAUSEI ELECTRICAL FAILURE -SECURITY COMPUTER # Ho Low level of knowledge HDO/RDO ACTION: REG 3. D. DANIELSON A Breakers were manually opened. DESCRIPTIONS LOST SECURITY COMPUTERS FOR 3 SECONDS WHILE BRINGING SLAVE ON. RASON NOT FULLY UNDERSTOOD. COMPENSATORY MEASURES TAKEN. REACTOR Ops hade been looked at. AT ZERO POWER BOTH BEFORE AND AFTER THE EVENT. ........... CLASSIFICATION Looking for common denomination FACILITY BEAVER VALLEY 1 REGION: 1 DATE OF EVENT! 07/04/84 NOTIFIED NRCI M. WAHLENMAYER DATE NOTIFIED: 07/04/84 ENTERED REPORTI BAILEY tul + Souly didn't notice auxthing. TIME OF EVENT! 2238 ET TIME NOTIFIED: 2249 ET

8/7/84 Page 2

						rage 2	
LER No.	Related IRs	Description	Date of Incident(s)	LER Date Due or (Submitted)	Type of Incident	Involved Dept(s)	
SECURITY	(Cont.)						
#84-023-00	84-0589	Moderate loss of security - loss of security hardware	8/4/84	8/9/84	Equipment	Security	
RADIATION	MONITORS						
84-003-00	84-0376 84-0513	Inadvertent ESF actuation through failure of radiation element GT-RE-22 by loss of power and initiation of Containment Purge Isolation and Control Room Vent Isolation signals	6/15/84 7/12/84	(7/16/84)	Equipment/ Procedure	Operations	
84-004-00 (Note 2)	84-0385	Inadvertent ESF actuation apparently caused by I&C working on radiation element GT-RE-33 initiating CPIS and CRVIS	6/17/84	(7/16/84)	Personnel	I&C	
84-006-00	84-0393	Loss of sample flow and inoperability of radiation monitor GT-RE-21B between 0803 and 1426; violation of Tech Specs	6/18/84	(7/18/84)	Personnel	Operations Health Phys	
84-006-01	84-0393	Correction of typographical errors in LER-84-006-00	6/18/84	(7/25/84)	Personnel	Operations Health Phys	
84-011-00	84-0459	Inadvertent ESF actuation through failure of radiation elements GK-RE-04, GT-RE-31, and GT-RE-33 by loss of power initiating Containment Purge Isolation signal and Control Room Vent Isolation signal	7/4/84	8/3/84	Personnel	Nuclear Opr	
84-018-00	84-0536	Inadvertent ESF actuation from radiation monitors GK-RE-05 and GG-RE-27 (CRVIS and FBVIS)	7/18/84	8/17/84	Equipment	16C	

DONALD F BCHNELL

July 9, 1984

MAILING ADDRESS
F D POX 146
ET LOUIS MIESOURI 65166

TO: All Personnel with Unescorted Access to the Callaway Plant

## ACTS OF VANDALISM OR SABOTAGE

Receipt of an operating license places a responsibility on each of us that must be fully understood. Any malicious act of vandalism or sabotage at a nuclear power plant that could jeopardize the safety of the general public, plant personnel or plant safety is a violation of Federal and State laws and will be dealt with in a severe manner by Union Electric Company. You should be aware that penalties under the law may be extended to individuals who are passively involved (have information but fail to report it) as well as to those who are actively involved in acts of vandalism or sabotage. Unauthorized alteration of valve or breaker alignment is so categorized, irrespective of the actual consequences of the alteration. Such violations can involve penalties of up to \$10,000 and 10 years imprisonment.

I would hope that acts of this kind will not occur at Callaway. However, be advised that Union Electric Company will exercise the necessary resources including the use of plant security forces, as well as local, State and Federal law enforcement agencies in dealing with such acts. We call upon each of you to assist us in identification of any person engaged in unauthorized or suspisious activities which might be considered vandalism or sabotage. If you witness such an act or have information relevant to known or suspected acts of vandalism or sabotage, you are obliged to report it to your management.

I am sure that the vast majority of people at the site want to continue Callaway's reputation as an exceptional plant as we commence operation. Through your continuing occperation, we can achieve this goal. I ask for your strong support in this matter which is crucial to the well-being of the Callaway Plant.

Donald F. Schnell

...s/jjw