

Appendix

NOTICE OF VIOLATION

Wisconsin Electric Power Company

Docket No. 50-266

Docket No. 50-301

As a result of the inspection conducted on August 1 to September 30, 1984, and in accordance with the General Policy and Procedures for NRC Enforcement Actions, (10 CFR Part 2, Appendix C), the following violation was identified:

Technical Specification 15.6.8.1 states in part, "the plant shall be operated and maintained in accordance with approved procedures." ICP 10.2, Routine Maintenance Procedure Removal of a Safeguards or Protection Sensor From Service, step 5.3 states "do the required bypassing of control functions".


Contrary to the above, on September 28, 1984, at 11:37 a.m. operations personnel removed the instrument power fuses for source range channel 31, a protection sensor, without placing the level trip switch in bypass.

This is a Severity Level V violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

OCT 16 1984

Dated \_\_\_\_\_

  
\_\_\_\_\_  
W. D. Shafer, Chief  
Projects Branch 12

8411130392 841016  
PDR ADOCK 05000266  
Q PDR