



35 FEB 11 AIO: 44

**Florida
Power**
CORPORATION

February 6, 1985
3F0285-07

Dr. J. N. Grace
Regional Administrator, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, N.W., Suite 2900
Atlanta, GA 30323

Subject: Crystal River Unit 3
Docket No. 50-302
Operating License No. DPR-72
I.E. Bulletin 84-02
Revised Response 2
Failure of GE Type HFA Relays In Use In Class IE Safety Systems

Dear Sir:

On June 7, 1984, Florida Power Corporation (FPC) responded to the subject I.E. Bulletin (3F0684-05). A revised response which incorporated additional information to clarify the actions taken by FPC to address the concerns in the bulletin was submitted on July 18, 1984 (3F0784-12). That revised response indicated that a review of past operating history and manufacturer's recommendations for relays used in similar applications as described in the bulletin, or relays with similar materials used for safety-related functions would be performed. The results of the review, along with any required corrective actions and schedules, were to be submitted to your office by February 28, 1985. However, due to extensive manpower required to prepare for the upcoming refueling outage at Crystal River Unit 3, this information will not be available until June 30, 1985. The information will be submitted to your office at that time.

Sincerely,

G. R. Westafer
Manager, Nuclear Operations
Licensing and Fuel Management

DG/mlg

8503010182 850206
PDR ADOCK 05000302
Q PDR

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE-11 1/0