

ENCLOSURE 1

NOTICE OF VIOLATION

Tennessee Valley Authority
Sequoyah Units 1 and 2

Docket Nos. 50-327 and 50-328
License Nos. DPR-77 and DPR-79

The following violation was identified during an inspection conducted on October 6 - November 5, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1 requires that written procedures be established, implemented and maintained covering activities referenced in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978. Paragraph 8 of Appendix A of Regulatory Guide 1.33 requires specific procedures for surveillance tests. Surveillance Instruction SI-258.2 was established to conduct surveillance activities on safety-related breakers.

Contrary to the above, as of October 19, 1984, adequate procedures were not established in that Surveillance Instruction SI-258.2 failed to provide cautionary information in an appropriate manner to ensure maintenance of control power to diesel generator 2A-A during testing of breaker 213 on 125 VDC Vital Battery Board III. This resulted in an inadvertent auto start of all diesel generators when control power to diesel generator 2A-A was removed.

This is a Severity Level V violation (Supplement I). This violation applies to both units.

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: DEC 12 1984

8503060337 850204
PDR ADOCK 05000327
G PDR