

ENCLOSURE 1

NOTICE OF VIOLATION

Georgia Power Company
Hatch Units 1 and 2

Docket Nos. 50-321 and 50-366
License Nos. DPR-57 and NPF-5

The following violation was identified during an inspection conducted on August 21-24, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification, Section 6.8.1.f requires written procedures to be established, implemented and maintained covering the fire protection program implementation.

Procedure HNP-1-3372-E, Rev. 0, Fire Protection Hydrant House Inspection, Section G. - 60 Day Inspection, requires that two 50 ft. sections of 2½" hose connected together, be arranged in an accordian fold on the lower shelf, and that equipment found to be defective or in need of repair be replaced or repaired prior to completion of the inspection.

Contrary to the above, on August 23, 1984, the hoses inside hydrant houses 2 and 4 were not arranged in accordance with the procedure and in hydrant house 2, a hydrant wrench was found with a severely bent handle and another one with a handle broken off.

This is a Severity Level V violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: SEP 17 1984