

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

September 25, 1984

BLRD-50-438/82-04
BLRD-50-439/82-04

34 SEP 28 P 1 : 36

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - BONNET STUDS IMPROPERLY TORQUED ON
DECAY HEAT REMOVAL VALVES - BLRD-50-438/82-04, BLRD-50-439/82-04 -
THIRD SUPPLEMENTAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on December 22, 1981 in accordance with 10 CFR 50.55(e) as NCR 1686. This was followed by our interim reports dated January 20, April 15, June 28, August 24, and November 1, 1982 and January 10, 1983, our final report dated April 13, 1983 and our supplemental reports dated December 22, 1983 and February 1, 1984. Below is our third supplemental report. We consider 10 CFR Part 21 applicable to this deficiency.

As discussed with NRC-OIE Inspector S. Weise on September 13, 1984, the date of September 15, 1984 for completion of corrective actions indicated in our final report on this matter would not be met. All bonnet studs have been torqued, but studs for one valve were inadvertently overtorqued necessitating the procurement of additional material to redo the work. The corrective action on this matter will be completed by December 31, 1984.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

DS Kammer

for L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8411160627 840925
PDR ADDOCK 05000438
S PDR