

October 29, 1984
(NMP2L 0221)


Mr. R. W. Starostecki, Director
U. S. Nuclear Regulatory Commission
Region I
Division of Project and Resident Programs
631 Park Avenue
King of Prussia, PA 19406

Re: Nine Mile Point - Unit 2
Docket No. 50-410

Dear Mr. Starostecki:

Enclosed is a final report, in accordance with 10CFR50.55(e), for the problem concerning sockolets supplied by Bonney-Forge. This problem was reported via tel-con to S. Collins of your staff on October 1, 1984.

Very truly yours,



C. V. Mangan
Vice President
Nuclear Engineering and Licensing

CVM/GG/pbd

xc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555

R. A. Gramm, NRC Resident Inspector
Project File (2)

8411190098 841029
PDR ADOCK 05000410
S PDR

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
DOCKET NO. 50

Final Report for a Problem
Concerning Sockolets (55(e)-84-43)

Description of the Problem

The problem pertains to the sockolets supplied by Bonney Forge - Gult & Western Manufacturing Company through Guyon Alloys, Incorporated to the Nine Mile Point - Unit 2 site under Purchase Order No. NMP2-FPO-12345. Guyon Alloys informed Niagara Mohawk that it has received a notification from Bonney Forge advising that some material has been furnished to Guyon Alloys with incomplete documentation. Guyon Alloys identified items that may have been manufactured from unqualified stock material. Guyon Alloys has provided a list of the suspect material supplied to the Nine Mile Point - Unit 2 site. These items are documented in Nonconformance and Disposition Report No. 8147.

Analysis of Safety Implications

A detailed analysis of safety implications was not performed because the corrective action outlined below is being taken. However, since these sockolets did not meet ASME code requirements, a possibility exists that their use in safety-related applications may have adversely affected the safety of operations of the plant.

Corrective Action

1. All fittings installed in Quality Assurance Category I applications will be replaced with approved material.
2. The fittings that were to be used in Category I applications but had not been installed will be scrapped.

These corrective actions will be completed in accordance with Nonconformance and Disposition Report No. 8147.