

1/12/73 Complete oil Change 8070 hrs.

2/6/74 Added 1 barrel of lube oil at 9257 hrs
Burns - Field

2/11/74 Added 1 Barrel of lube oil at 9337 hrs
Gen. oil Added & water added.
Burns - Kort

2-20-74 MP-8 9407 Hrs
Dust Bin Blower Failure Causing Generator
Failure Generator Coils 3-4 o'clock
Position BAO, STARTED PREPARATIONS FOR GEN. 4
Dust Bin Blower Removal #404 D71
Generator SIN OUT #72-B-3-1155

2-22-74 MP-8 9407 Hrs
MONTHLY QUARTERLY INSPECTION

2-25-74 Added 2 bbls. oil to generator AT 9407 hrs.

KORT-BURNS

2/28/74 INSTALLED GENERATOR SET #43K31128 INSTALLED
9407 HRS DUST BIN BLOWER SET #404 D71.

KEHEE + CONNOLLY (WAC)

3-15-74 MP-8 INSTALL DUST BIN BLOWER DRIVE SHAFT.

3-18-74 INSTALLED DUST BIN BLOWER EXPANSION GASKET
KINGSLEY KORT

3/22/74 INSTALLED NEW FAN BELT SET. INSPECTED FAN COMPARTMENT
9417 HRS FOUND OK. FOUND BAD LASH ADJUSTERS #11 AND #12 CYLINDERS.
BOTH GEN. END.

KEHEE + CONNOLLY

50-322 06-4 I-SC-LP-6
7/31/84

NUCLEAR REGULATORY COMMISSION

Docket No. 50-322-06-4 Official Exh. No. _____
In the matter of LLCO - Low Power
Staff _____ IDENTIFIED ☒
Applicant _____ RECEIVED ☒
Intervenor ☒ REJECTED _____
Cont'g Off'r _____ DATE 7/31/84
Contractor _____ Witness James H. Lewis
Other _____
Reporter Stevens - Clark - Taylor

