

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

85 JAN 10 1985 8:15
January 4, 1985

BLRD-50-438/82-04
BLRD-50-439/82-04

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - BONNET STUDS IMPROPERLY TORQUED ON
DECAY HEAT REMOVAL VALVES - BLRD-50-438/82-04, BLRD-50-439/82-04 -
FOURTH SUPPLEMENTAL REPORT


The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on December 22, 1981 in accordance with 10 CFR 50.55(e) as NCR 1686. This was followed by our interim reports dated January 20, April 15, June 28, August 24, and November 1, 1982 and January 10, 1983, our final report dated April 13, 1983 and our supplemental reports dated December 22, 1983 and February 1 and September 25, 1984. Below is our fourth supplemental report. We consider 10 CFR Part 21 applicable to this deficiency.

As discussed with NRC-OIE Inspector S. Weise on December 14, 1984, the date of December 31, 1984 for completion of corrective actions indicated in our final report on this matter would not be met. The replacement material referenced in our third supplemental report will not be sent by Borg Warner until January 1985. The corrective action on this matter will be completed by April 1, 1985.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


J. W. Hufham, Manager
Licensing and Regulations

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

OFFICIAL COPY
IE 27
1/0

8501160036 850104
PDR ADOCK 05000438
S PDR

An Equal Opportunity Employer