USN DUKE POWER COMPANY P.O. BOX 33189 CHARLOTTE, N.C. 28242

HAL B. TUCKER VICE PRESIDENT NUCLEAR PRODUCTION

84 DEC 21 P1: b2cember 17, 1984

TELEPHONE (704) 373-4531

Mr. James P. C'Reilly, Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

Re: Catawba Nuclear Station, Units 1 & 2
Docket Nos. 50-413 and 50-414
Significant Deficiency No. 413-414/84-03

Dear Mr. O'Reilly:

It was stated in the final report, dated December 4, 1984, on Significant Deficiency No. 413-414/84-03, that corrective action has been implemented on the Unit 2 diesels. We regret that this statement was made in error. The inspection of the fuel pump drives for loose hubs on the Unit 2 diesels will be completed and the results forwarded to you by January 15, 1985.

Additionally, "Locktite 680" rather than Locktite "609" was used in the inspection of the Unit 1 drives; it will also be used in the inspection of the Unit 2 drives.

Very truly yours,

Hel B. Juke

Hal B. Tucker

LTP:slb

office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

Palmetto Alliance 2135½ Devine Street Columbia, South Carolina 29205 Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

Mr. Jesse L. Riley Carolina Environmental Study Group 854 Henley Place Charlotte, North Carolina 28207

NRC Resident Inspector Catawba Nuclear Station

8501160132 841217 PDR ADUCK 05000413 PDR

10 IE 27