

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Susquehanna Steam Electric Station - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 8 8	PAGE (3) 1 OF 0 1
--	--------------------------------------	----------------------

TITLE (4)
Fire Watch Not Performed as Required.

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)
1	2	0	6	8	4	8	4	0		0 5 0 0 0
										0 5 0 0 0

OPERATING MODE (9) 4

POWER LEVEL (10) 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8: (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.408(e)	<input type="checkbox"/> 80.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 80.38(a)(1)	<input type="checkbox"/> 80.73(a)(2)(v)	<input type="checkbox"/> 73.71(e)
<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 80.38(a)(2)	<input type="checkbox"/> 80.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
<input type="checkbox"/> 20.406(a)(1)(iii)	<input checked="" type="checkbox"/> 80.73(a)(2)(i)	<input type="checkbox"/> 80.73(a)(2)(vii)(A)	
<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 80.73(a)(2)(ii)	<input type="checkbox"/> 80.73(a)(2)(vii)(B)	
<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 80.73(a)(2)(iii)	<input type="checkbox"/> 80.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME T.P. Baileys	TELEPHONE NUMBER AREA CODE 7 1 1 7 5 1 4 2 1 - 1 3 2 4 1 1
----------------------	--

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
A	*	*	*	NO					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR
0 3	2 1 9	8 5

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

A fire watch was required in one area of the plant for two independent work activities. When one work activity was completed on December 6, 1984, the fire watch for the area was removed from the fire watch log. The fire watch log did not reference the two work activities. When the error was discovered on December 17, 1984, the fire watch was reinstated.

An evaluation is being conducted by the Operations Section to determine corrective actions to prevent recurrence. A supplement to this LER will be submitted by 3-29-85 to describe the corrective actions.

*Not Applicable.

IE 22

11

8501290054 850116
PDR ADOCK 05000388
S PDR

PP&L

SUSQUEHANNA STEAM ELECTRIC STATION
PO BOX 467, BERWICK, PA 18603


January 17, 1985

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 84-023-00
ER 100450 FILE 841-23
PLAS-027

Docket No. 50-388
License No. NPF-22

Attached is Licensee Event Report 84-023-00. This event was determined reportable per 10CFR50.73(a)(2)(i), in that a fire watch was not performed as required by Technical Specification Action Statement 3.7.6.4.a during the period of December 6, 1984 to December 17, 1984. The fire watch was reinstated immediately upon discovery of the error.



H.W. Keiser
Superintendent of Plant-Susquehanna.

TPB/pjg

cc: Dr. Thomas E. Murley
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Mr. R.H. Jacobs
Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

IE22

1/1