

MAY 30 1985

Docket No. 50-352

Philadelphia Electric Company  
ATTN: Mr. S. L. Daltroff  
Vice President, Electric Production  
2301 Market Street  
Philadelphia, PA 19101

Gentlemen:


Subject: Inspection Report No. 50-352/85-06

This refers to your letter dated May 8, 1985, in response to our letter dated April 10, 1985.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions were examined during inspection 50-352/85-24 and were found acceptable. Thus violations (352/85-06-02, 352/85-06-04 and 352/85-06-05) are considered closed.

Your cooperation with us is appreciated.

Sincerely,

  
Stewart D. Ebnetter, Director  
Division of Reactor Safety

cc:

V. S. Boyer, Senior Vice President, Nuclear Power  
John S. Kemper, Vice President, Engineering and Research  
G. Leitch, Station Superintendent  
Troy B. Conner, Jr., Esquire (Receives All 2.790 Information)  
Eugene J. Bradley, Esquire, Assistant General Counsel  
Limerick Hearing Service List  
Public Document Room (PDR)  
Local Public Document Room (LPDR)  
Nuclear Safety Information Center (NSIC)  
NRC Resident Inspector  
Commonwealth of Pennsylvania

OFFICIAL RECORD COPY

RL LIMERICK 85-06 - 0001.0.0  
05/22/85

8506140664 850530  
PDR ADOCK 05000352  
Q PDR

IE01

bcc:

Region I Docket Room (with concurrences)

Senior Operations Officer

Section Chief, DRP

P. Eselgroth, Shoreham, SRI

Section Chief, TPS, DRS

RI DRS  
Florek/djh

5/22/85

RI DRS  
Bettendhausen

5/22/85

RI DRS  
Ehner

5/22/85

OFFICIAL RECORD COPY

RL LIMERICK 85-06 - 0001.1.0  
05/22/85

Limerick Hearing Service List

Judge Helen F. Hoyt  
Atomic Safety and Licensing  
Board  
U.S. Nuclear Regulatory  
Commission  
Washington, D.C. 20555

Judge Richard F. Cole  
Atomic Safety and Licensing  
Board  
U.S. Nuclear Regulatory  
Commission  
Washington, D.C. 20555

Judge Jerry Harbour  
Atomic Safety and Licensing  
Board  
U.S. Nuclear Regulatory  
Commission  
Washington, D.C. 20555

Mr. Frank R. Romano  
61 Forest Avenue  
Ambler, Pennsylvania 19002

Mr. Robert L. Anthony  
P. O. Box 186  
103 Vernon Lane  
Moylan, Pennsylvania 19065

David Wersan, Esq.  
Assistant Consumer Advocate  
Office of Consumer Advocate  
1425 Strawberry Square  
Harrisburg, PA 17120

Steven P. Hershey, Esquire  
Community Legal Services, Inc.  
Law Center West  
5219 Chestnut Street  
Philadelphia, PA 19139

Martha W. Bush, Esquire  
Kathryn S. Lewis, Esquire  
Municipal Services Bldg.  
15th and JFK Blvd.  
Philadelphia, PA 19107

Mr. Marvin I. Lewis  
6504 Bradford Terrace  
Philadelphia, PA 19149

Phyllis Zitner  
LEA  
P. O. Box 761  
Pottstown, PA 19464

Docketing and Service Station  
Office of the Secretary  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Counsel for NRC Staff  
Office of the Executive Legal Director  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Philadelphia Electric Company  
ATTN: Edward G. Bauer, Jr.  
Vice President and  
General Counsel  
2301 Market Street  
Philadelphia, PA 19101

Charles W. Elliott, Esquire  
Brose and Postwistilo  
1101 Building  
11th and Northampton Streets  
Easton, PA 18042

Zori G. Ferkin  
Governor's Energy Council  
P. O. Box 8010  
Harrisburg, PA 17105

Troy B. Conner, Jr., Esquire  
Mark J. Wetterhahn, Esquire  
Conner & Wetterhahn  
1747 Pennsylvania Avenue  
Washington, D. C. 20006

Angus Love, Esquire  
101 East Main Street  
Norristown, PA 19401

Robert J. Sugarman, Esq.  
Sugarman, Denworth & Hellegers  
16th Floor Center Plaza  
101 North Broad Street  
Philadelphia, PA 19107

Spence W. Perry, Esquire  
Associate General Counsel  
Federal Emergency Management Agency  
500 C Street, S.W. Room 840  
Washington, DC 20472

Mr. Joseph H. White, III  
15 Ardmore Avenue  
Ardmore, PA 19003

Thomas Y. Au, Esquire  
Assistant Counsel  
Commonwealth of Pennsylvania  
DER  
505 Executive House  
P. O. Box 2357  
Harrisburg, PA 17120

Thomas Gerusky, Director  
Bureau of Radiation Protection  
Department of Environmental  
Resources  
5th Floor, Fulton Bank Bldg.  
Third and Locust Streets  
Harrisburg, PA 17120

# PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-5020

M. J. COONEY  
MANAGER  
NUCLEAR PRODUCTION  
ELECTRIC PRODUCTION DEPARTMENT

May 8, 1985

Docket No. 50-352

Inspection Report No. 50-352/85-06

Mr. Stewart D. Ebnetter, Director  
Division of Reactor Safety  
U.S. Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA 19406

Dear Mr. Ebnetter:

Your letter dated April 10, 1985 forwarded Inspection Report 50-352/85-06 for Limerick Generating Station. Appendix A of your letter addresses three items which do not appear to be in full compliance with Nuclear Regulatory Commission requirements. These items are restated below along with our response.

## Finding

- A. Code of Federal Regulations 10 CFR 50.54(3)(J) requires, in part, "Apparatus and mechanisms other than controls, the operation of which may affect the reactivity or power level of a reactor shall be manipulated only with the knowledge and consent of a licensed operator present at the controls". Licensee Administrative Procedure A-7 in Section 5.2.2 states similar requirements.

Contrary to the above, on January 25, 1985, instrumentation and controls personnel in the process of troubleshooting previous indication of erratic recirculation pump flow behavior caused an increase in recirculation pump flow, which increased reactor power, when connecting a recorder to the recirculation flow control circuit. This work was performed without the knowledge and consent of the licensed operators present at the controls.

This is a Severity Level IV Violation (Supplement 1).

~~8549158317~~  
7PP



Response

Failure to notify and obtain permission from Shift Operations personnel prior to troubleshooting the recirculation pump control circuit on January 25, 1985 deviated from normal practices of Instrumentation and Controls (I&C) personnel. On this occasion the technicians were working under the direction of the system engineer to clarify a problem with the Reactor Recirculation Flow indication. Although their activities resulted in the recirculation pump transient, the technicians had no reason to believe that installing the recorder to test jacks would have that effect. The root cause of the event was the use of a temporary test device (Gould Strip Chart Recorder, Model 2800W) which does not have an internal isolation circuit.

The initial corrective action taken to rectify the failure of I&C technicians to properly communicate with Shift Operators before initiating work was to conduct a training session with I&C technicians. The training session discussed the subject event in detail and stressed the importance of informing the Control Room Operators of activities planned when troubleshooting a problem. In addition, a new procedure has been issued to control troubleshooting activities for safety related equipment which requires obtaining work group supervisor permission prior to work. One objective of this procedure is to enhance communication with Shift Operators. To ensure proper implementation of this new troubleshooting control procedure specific training sessions have been conducted with applicable work groups on site.

Based on the corrective actions described, full compliance with 10 CFR 50.54(3)(J) has been achieved.

Finding

- B. Technical Specification 6.8.1.a requires, in part, "written procedures be established as recommended in Appendix A of Regulatory Guide 1.33, Revision 2". Regulatory Guide 1.33, Revision 2, in Appendix A, paragraph 9.e, recommends, in part, "general procedures for the control of maintenance which includes items such as a method for obtaining permission and clearance from operation personnel to work".

Contrary to the above, as of January 25, 1985 controls to assure that permission is obtained from operations personnel prior to performing troubleshooting activities are not contained in general procedures.

This is a Severity Level IV Violation (Supplement I).

Response

While troubleshooting a problem with the "B" Recirculation Pump control circuit on January 25, 1985, I&C technicians deviated from the normal practice of coordinating these activities with the shift operators. During this troubleshooting activity a recirculation pump speed and flow transient occurred which was caused by use of a recording test instrument. It was not known that this particular temporary test instrument (Gould Strip Chart Recorder, Model 2800W) did not have an internal isolation circuit.

The consequences of this inadvertent event were limited and the 5% reactor power limit was not exceeded. The limited consequences were attributed mainly to backup administrative controls in place which had the pump electronic and mechanical speed control stops set at 48% and 50% speed respectively.

The initial corrective action taken as a result of this event was to remove this particular test strip chart recorder from use and to verify that no other authorized test equipment lacked an internal isolation circuit. Although the Shift Operator was not informed of the activity at the time, the transient would not have been prevented if communications had been established. As described in our response to Finding A., an additional corrective action taken was to conduct a training session with I&C technicians. The training session discussed the transient event in detail and stressed the importance of informing the Shift Operators of activities planned when troubleshooting a problem.

To improve troubleshooting activities a specific control procedure has been issued. The objectives of this procedure include; 1) establish a bound for troubleshooting activities, 2) enhance communication with Shift Operations, 3) document restoration, 4) control troubleshooting activities by obtaining work group supervisor permission, and 5) ensure record retention. To ensure proper implementation of this new troubleshooting control procedure, specific training sessions were conducted with applicable work groups on site.

Based upon the actions described to improve controls for troubleshooting activities, full compliance has been achieved.

Finding

- C. License NPF-27 requires, in part, "conducting the post-fuel loading initial test program without deviating from the initial test program administrative procedures". Initial test program Administrative Procedure A-202 requires, in part, in Section 5.4, that the plant be placed in a suitable hold condition when a test exception involves a Level 1 acceptance criteria failure, the startup test group supervisor obtains a resolution and convenes a Test Review Committee (TRC) or Plant Operational Review Committee (PORC) meeting to review and recommend approval of the resolution and hold condition, document such action, and the Station Superintendent approves the hold condition and provides explicit approval to exceed the approved hold condition".

Contrary to the above, as of February 7, 1985, two examples were identified that failed to follow the Administrative Procedure.

1. A Level 1 acceptance criterion failure identified as TER-22 on January 5, 1985 did not have documented evidence that the review of the resolution and hold condition satisfied the requirement for TRC or PORC review.
2. Level 1 acceptance criterion failure, identified as TER-29 on January 11, 1985, did not result in placing the plant in a suitable hold condition, TRC or PORC review and recommendation for approval of the resolution of the test exception and hold condition, Station Superintendent approval of the hold condition, or explicit approval from the Station Superintendent to exceed the hold condition.

"The safety impact of this violation was minimal because the licensee did have authorization by the Station Superintendent for TER-22 and did have analysis available (although unauthorized) at the time of TER-29, which was subsequently authorized for use, that accepted the data. However, the actions were not fully in accordance with the administrative procedure implementing the startup program.

Therefore, the violation is being issued and is classified as a Severity Level V Violation (Supplement I).

Response

Although it was not properly documented, the Level 1 acceptance criterion failure identified in TER-22 and its resolution were discussed extensively with PORC members and Electric Production Quality Assurance (EPQA) representatives. As stated in the



body of the inspection report, the inspector agreed that the extent of review conducted met the intent of the administrative procedure. Subsequent to this occurrence, TRC meeting 85-01 and PORC meeting 85-19 officially reviewed and approved the resolution of TER-22 which revised the pipe expansion Level 1 acceptance criteria from 200 mils to 385 mils for all test temperatures. TER-22 was officially and properly closed on February 15, 1985.

TER-29 incorrectly documented a failure to meet a Level 1 acceptance criteria during implementation of STP-17.3 at 920 psig. Since this failure had previously been documented by TER-22 at 450 Degrees F and a revised acceptance criterion had been provided, Shift test personnel considered its resolution to also apply to performance of STP-17.3 at 920 psig. Section 5.4.4.1.a.1 of procedure A-202 permits a TER to apply to more than one subtest if the same acceptance criteria is affected in each of the subtests. During final review and approval of TER-22 the TRC and PORC agreed that it also applied to the performance of STP-17.3 at rated reactor temperature and documented that conclusion. Accordingly, reference to a Level 1 acceptance criterion failure in TER-29 was deleted. The remaining Level 2 acceptance criterion failures in TER-29 were reviewed and their resolution to accept "as is" was approved by the TRC on April 24, 1985.

In addition to the actions already described, a training session was conducted to familiarize Startup Group test personnel with these events to prevent similar administrative problems in the future. Specifically, the objectives were: 1) ensure all test personnel understood the actual events; 2) discuss the various interpretations of administrative requirements relevant to the events; 3) provide specific directions on how to administratively comply with similar events in the future; and 4) provide additional guidance to test program personnel on test implementation and processing of test results.

Further improvements have been achieved by setting goals for more timely review of TER(s) by the TRC and PORC. On March 13, 1985, during the exit meeting for NRC inspection 352/85-14, the inspector reported that much improvement has been achieved regarding administrative controls for the startup test program implementation and test results review.

Administrative Procedure requirements for TER(s) 22 and 29 have been completed satisfactorily and full compliance with Administrative Procedure A-202 has been achieved.

Mr. Stewart D. Ebnetter

May 8, 1985

Page 6

Should you have any questions or require further information, please contact us.

Very truly yours,

Original signed by  
M. J. COONEY

cc: Dr. T. E. Murley, Administrator  
Mr. J. T. Wiggins, Resident Site Inspector  
See Attached Service List

cc: Judge Helen F. Hoyt  
Judge Jerry Harbour  
Judge Richard F. Cole  
Troy B. Conner, Jr., Esq.  
Ann P. Hodgdon, Esq.  
Mr. Frank R. Romano  
Mr. Robert L. Anthony  
Ms. Phyllis Zitner  
Charles W. Elliott, Esq.  
Zori G. Ferkin, Esq.  
Mr. Thomas Gerusky  
Director, Penna. Emergency Management Agency  
Angus Love, Esq.  
David Wersan, Esq.  
Robert J. Sugarman, Esq.  
Martha W. Bush, Esq.  
Spence W. Perry, Esq.  
Jay M. Gutierrez, Esq.  
Atomic Safety & Licensing Appeal Board  
Atomic Safety & Licensing Board Panel  
Docket & Service Section (3 Copies)  
James Wiggins  
Timothy R. S. Campbell

January 16, 1985