

MAY 17 1985

Docket No. 50-237

Docket No. 50-249

Commonwealth Edison Company

ATTN: Mr. Cordell Reed

Vice President

Post Office Box 767

Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by Mr. G. A. Brown and others of this office on April 22 through 24, 1985, of activities at Dresden Nuclear Generating Station, Units 2 and 3, authorized by NRC Operating Licenses No. DPR-19 and DPR-25, and to the discussion of our findings with Mr. D. Scott and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection. However, weaknesses were identified which will need corrective action by your staff. These weaknesses are summarized in the Appendix to this letter. As required by 10 CFR 50, Appendix E (IV.F), any weaknesses that are identified must be corrected. Accordingly, please advise us within 45 days of the date of this letter of the corrective actions you have taken, or plan to take, regarding these weaknesses, including the estimated dates of completion.

The responses directed by this letter are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act, PL 96-115.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosures will be placed in the NRC Public Document Room.


8505210365 850517
PDR ADOCK 05000237
G PDR

IE35
11

MAY 17 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



C. J. Paperiello, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosures:

1. Appendix, Exercise Weaknesses
2. Inspection Reports
No. 50-237/85011(DRSS)
No. 50-249/85010(DRSS)

cc w/encls:

D. L. Farrar, Director
of Nuclear Licensing
D. J. Scott, Station
Superintendent
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Phyllis Dunton, Attorney
General's Office, Environmental
Control Division
D. Matthews, EPB, OIE
W. Weaver, FEMA V

RIII

Brown/kr
05/15/85

RIII
TO
Ploski

RIII
NRW.
Williamsen

RIII

Phillips

RIII

Chrissotimos

RIII

Paperiello
5/17/85

APPENDIX

EXERCISE WEAKNESSES

1. Access control to the TSC was not accomplished in a timely manner nor was it performed in a satisfactory manner after it was established. (50-237/85011-01 and 50-249/85010-01)
2. Implementation of shift staffing and augmentation was not accomplished in a timely manner. There was a breakdown in the call tree. (50-237/85011-02 and 50-249/85010-02)
3. Evacuation of non-essential personnel was not ordered in a timely manner following completion of the simulated accountability of onsite personnel. (50-237/85011-03 and 50-249/85010-03)
4. Poor radiological control technique was observed during the handling of the radiological injury. (50-237/85011-04 and 50-249/85010-04)
5. The EOF failed to provide adequately detailed followup messages in accordance with the licensee's EOF Procedure EOF-1, paragraphs 4.2.f and 5.2.f. (50-237/85011-05 and 50-249/85010-05)