

January 18, 1993

2CAN019302

U. S. Nuclear Regulatory Commission Document Control Desk Mail Station P1-137 Washington, DC 20555

Subject: Arkansas Nuclear One - Unit 2

Docket No. 50-368 License No. NPF-6

Inservice Inspection Outage

Summary Report

Gentlemen:

Article IWA-6230, Section XI of the ASME Code requires the Owner to submit an inservice inspection (ISI) summary report. The scope of the report is to provide the inspection results of the Class 1 and 2 pressure retaining components and their supports. This report is due within 90 days of the completion of the ISI conducted during a refueling outage.

Attachment 1 provides the Form NIS-1 "Owner's Report For Inservice Inspections." The ISI was performed during the ninth refueling outage (2R9) for Arkansas Nuclear One, Unit 2 (ANO-2). The outage was completed on October 20, 1992. This form was prepared in accordance with Section XI of the Code.

Attachment 2 provides a summary of the ISI component examination. The forms NIS-2 "Owner's Report for Repairs or Replacements" are provided in Attachment 3.

Should you have any questions regarding this submittal, please contact me.

Very truly yours,

James J. Fisicaro Director, Licensing

JJF/JJD/klc Attachments

220040

9301250177 930118 PDR ADDCK 05000368 PDR A047 /

U. S. NRC January 18, 1993 Page 2

cc: Mr. James L. Milhoan
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

NRC Senior Resident Inspector Arkansas Nuclear One - ANO-1 & 2 Number 1, Nuclear Plant Road Rusaellville, AR 72801

Mr. Roby Bevan
NRR Project Manager, Region IV/ANO-1
U. S. Nuclear Regulatory Commission
NRR Mail Stop 11-D-23
One White Flint North
11555 Rockville Pike
Rockville, Maryland 20852

Mr. Thomas W. Alexion
NRR Project Manager, Region IV/ANO-2
U. S. Nuclear Regulatory Commission
NRR Mail Stop 11-D-23
One White Flint North
11555 Rockville Pike
Rockville, Maryland 20852