

Teletcopy

79 JUL 3 AIO: 27

Mr. J. P. O'Reilly, Director
USNRC Region II
Office of Inspection and Enforcement
101 Marietta St., Suite 3100
Atlanta, GA 30303

RE: Docket 50-302 License LPR-72

This will confirm a report made to Mr. Donald Price of your office at 1400, 2 July 1979, that at 1000 2 July 1979, it was determined that ninety-two (92) pipe supports have thus far been identified as inadequate based on the guidelines of I & E Bulletins 79-02 and 79-02 revision 1. This is reported under Technical Specification 6-9-1-81.

The effected supports are being redesigned and installed under modification 79-6-86. Three of the ninety-two supports (SWH-522, PCH-101, DHM-645), have a safety factor less than one (1) and have been identified as a constraint for startup.

Guy P. Beatty, Jr.
Nuclear Plant Manager
Crystal River Unit 3
Florida Power Corporation

xc W. P. Stewart
J. C. Hobbs
D. R. Quick

- E. P. O'REILLY
- ~~D. THOMPSON~~
- E. M. UPRIGHT
- P. D. CHENDEMI
- W. B. KENNA
- F. J. LONG
- E. E. MURPHY
- B. T. SUTHERLAND
- K. M. CLARK
- Lewis*
- Jenkins*
- Quick*

A0 2

7908800775

60