

SEP 19 1985

Docket No. 50-254
Docket No. 50-265

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by Mr. G. Brown and others of this office on August 26-28, 1985, of activities at the Quad Cities Nuclear Generating Station, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-29 and DPR-30, and to the discussion of our findings with Mr. N. Kalivianakis and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

However, during this emergency preparedness exercise inspection, certain weaknesses were identified which will require corrective actions. These weaknesses are identified in the appendix to this letter. As required by 10 CFR Part 50, Appendix E (IV.F), any weaknesses that are identified must be corrected. Accordingly, you are requested to submit a written statement within 30 days of the date of this letter describing your planned actions for correcting the weaknesses identified in the appendix.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room.

The responses directed by this letter are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

*IE351/1
delete R111*

8509270115 850919
PDR ADOCK 05000254
Q PDR

Commonwealth Edison Company

2 SEP 19 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by W.D. Shafer"


W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch


Enclosures:

1. Appendix, Exercise Weaknesses
2. Inspection Reports
 No. 50-254/85015(DRSS); and
 No. 50-265/85017(DRSS)


cc w/enclosures:


D. L. Farrar, Director
of Nuclear Licensing
N. Kalivianakis, Plant Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Phyllis Dunton, Attorney
General's Office, Environmental
Control Division
D. Matthews, EPB, OIE
W. Weaver, FEMA, RV
M. Carroll, FEMA, RVII


Brown/l
09/12/85


RIII
Shea


RIII
Ploski


RIII
Smith


RIII
Phillips


RIII
Wright


RIII
Shafer

APPENDIX

EXERCISE WEAKNESSES

1. Some workers were not adequately instructed on proper radiological protection methods. (Paragraph 5.c) (254/85015-02; 265/85017-02)
2. Initial offsite Protective Action Recommendations (PAR) associated with the Site Area Emergency and General Emergency declarations were inadequate. Errors were made in either formulating, reviewing, documenting or communicating the PARs. (Paragraph 5.e) (254/85015-04; 265/85017-04)
3. Information disseminated by the JPIC was inaccurate and inadequate. (Paragraph 5.f) (254/85015-05; 265/85017-05)