

SSER

Task: Allegation A-341

Reference No.: 4-84-A-51-2

Characterization: The allegation is that deformed cable trays were "cinched up with a come-a-long" in order to install the cable tray covers.

Assessment of Allegation: The implied significance of this allegation is that the method of using a mechanical device to compress cable trays to install the covers may have caused damage to cables installed in the trays.

Since the allogger did not give specific locations where such instances occurred, the NRC staff inspected 1800 feet of cable tray as follows:

- o Reactor Auxiliary Building: +21, -4, and -35, elevations.
- o Reactor Containment Building: +21, +35, and +46 elevations.

The NRC staff's inspection revealed no instances of damaged or deformed cable trays that would have indicated damaged cables.

This allegation has neither safety significance nor generic implications.

Potential Violations: None.

Actions Required: None.

References: None.

Statement Prepared By:

William S. Marini

Date

Reviewed By:

Team Leader

Date

Reviewed By:

Site Team Leader(s)

Date

Allegation A-341

- 2 -

Approved By:

Task Management

Date

Document Name:
SSER A-341

Requestor's ID:
JOHNNIE

Author's Name:

Document Comments:

SSER

Task: Allegation A-341

Reference No.: 4-84-A-51-2

Characterization: The allegation is that deformed cable trays were "cinched up with a come-a-long" in order to install the cable tray covers.

Assessment of Allegation: The implied significance of this allegation is that the method of using a mechanical device to compress cable trays to install the covers may have caused damage to cables installed in the trays.

Since the allegor did not give specific locations where such instances occurred, the NRC staff inspected 1800 feet of cable tray as follows:

- o Reactor Auxiliary Building: +21, -4, and -35, elevations.
- o Reactor Containment Building: +21, +35, and +46 elevations.

The NRC staff's inspection revealed no instances of damaged or deformed cable trays that would have indicated damaged cables.

This allegation has neither safety significance nor generic implications.

[Potential Violations: None.]

Actions Required: None.

References: None

Statement Prepared By:

William S. MariniDate

Reviewed By:

Team LeaderDate

Reviewed By:

Site Team Leader(s)Date

Approved By:

Task ManagementDate

7

Document Name:
SSER A-341

Requestor's ID:
CONNIE

Author's Name:

Document Comments:

SSER

Task: Allegation A-341

Reference No.: 4-84-A-51-2

Characterization: The allegation is that deformed cable trays were "cinched up with a come-a-long" in order to install the cable tray covers.

Assessment of Allegation: The implied significance of this allegation is that the method of using a mechanical device to compress cable trays to install the covers may have caused damage to cables installed in the trays.

Since the alleged did not give specific locations where such instances occurred, the NRC staff inspected 1800 feet of cable tray as follows:

- o Reactor Auxiliary Building: +21, -4, and -35, elevations.
- o Reactor Containment Building: +21, +35, and +46 elevations.

The NRC staff's inspection revealed no instances of damaged or deformed cable trays that would have indicated damaged cables.

This allegation has neither safety significance nor generic implications.

Potential Violations: None.

Actions Required: None.

References: None

Statement Prepared By:

William S. Marini

Date

Reviewed By:

Team Leader

Date

Reviewed By:

Site Team Leader(s)

Date

Approved By:

Task Management

Date

SSER

Task: Allegation A-341

Reference No.: 4-84-A-51-2

Characterization: The allegation is that deformed cable trays were "cinched up with a come-a-long" in order to install the cable tray covers.

Assessment of Allegation: The implied significance of this allegation is that the method of using a mechanical device to compress cable trays to install the covers may have caused damage to cables installed in the trays.

Since the allexer did not give specific locations where such instances occurred, the NRC staff inspected 1800 feet of cable tray as follows:

- o Reactor Auxiliary Building: +21, -4, and -35, elevations.
- o Reactor Containment Building: +21, +35, and +46 elevations.

The NRC staff's inspection revealed no instances of damaged or deformed cable trays that would have indicated damaged cables.

This allegation has ^{SSER} neither safety significance nor generic implications.

Potential Violations: None.

Actions Required: None.

References: None

FINAL SSER ROUTING

A341

Revision :	0	1	2	3
Denny Crutchfield	<i>[Signature]</i>			
Jim Gagliardo	<i>[Signature]</i>			

OK Final do not re-route

Statement Prepared By:

William S. Marini

Date

Reviewed By:

Team Leader

Date

Reviewed By:

Site Team Leader(s)

Date

Approved By:

Task Management

Date

Document Name:

SSER A-341

✓4

Requestor's ID:

CONNIE

Author's Name:

Document Comments:

SSER

Task: Allegation A-341

Reference No.: 4-84-A-51-2

Characterization: The allegation is that deformed cable trays were "cinched up with a come-a-long" in order to install the cable tray covers.

Assessment of Allegation: The implied significance of this allegation is that the method of using a mechanical device to compress cable trays to install the covers may have caused damage to cables installed in the trays.

Since the allerger did not give specific locations where such instances occurred, the NRC staff inspected 1800 feet of cable tray as follows:

- o Reactor Auxiliary Building: +21, -4, and -35, elevations.
- o Reactor Containment Building: +21, +35, and +46 elevations.

The NRC staff's inspection revealed no instances of damaged or deformed cable trays that would have indicated damaged cables.

This allegation has neither safety significance nor generic implications.

[Potential Violations: None.] 4

Actions Required: None.

References: None

Statement Prepared By:

William S. Marini

Date

Reviewed By:

Team Leader

Date

Reviewed By:

Site Team Leader(s)

Date

Approved By:

Task Management

Date