



VIRGINIA POWER

July 31, 1985

CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

Mr. Ray R. Jenkins  
State Water Control Board  
Piedmont Regional Office  
2201 West Broad Street  
Richmond, Virginia 23230

Surry Power Station - NPDES Permit Exception

Dear Mr. Jenkins:

This is to provide additional information concerning the NPDES permit exception at our Surry Power Station that was previously reported to you by phone on July 19, 1985.

At approximately 10:00 a.m. on July 19, 1985 station personnel noted that the flow recording pen for Outfall 011, the sewage treatment plant, was not responding to input voltage. It was determined that the failure was due to malfunctioning flow integrator parts. As corrective action, replacement parts were ordered, and repairs will be made upon receipt. Flows from this outfall will be estimated in the interim, using a non-recording flow meter associated with the sewage treatment plant.

If you have any questions regarding this exception, please do not hesitate to contact this department.

Very truly yours,

John A. Taylor, Ph.D.  
Manager  
Water Quality *JA*

- cc: Dr. J. Nelson Grace, USNRC - Docket Nos. 50-280/50-281
- Mr. Harold R. Denton, USNRC - Docket Nos. 50-280/50-281 ✓
- Mr. Donald J. Burke, USNRC - Docket Nos. 50-280/50-281

8508090251 850731  
PDR ADOCK 05000280  
S PDR

*IE23*  
*1/0*