

DMB

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

85 OCT 20 P12:43

W. L. STEWART
VICE PRESIDENT
NUCLEAR OPERATIONS

October 21, 1985

Dr. J. Nelson Grace
Regional Administrator
Region II
U. S. Nuclear Regulatory Commission
Suite 2900
101 Marietta St., N.W.
Atlanta, Georgia 30323


Serial No. 85-543A
NAPS/JHL
Docket Nos. 50-338
50-339
License Nos. NPF-4
NPF-7

Dear Dr. Grace:

In our response to Inspection Report Nos. 50-338/85-16 and 50-339/85-16, dated September 19, 1985 (Serial No. 85-543), we committed to issue a directive to operations personnel requiring adherence to station procedures. This commitment was in relation to having a valve lineup problem on the casing cooling subsystem and was to be accomplished by October 1, 1985.

Due to an administrative error, the directive was not issued to operations personnel by October 1, 1985. The operations directive was issued October 14, 1985.

Very truly yours,


W. L. Stewart

No Attachment

- cc: Mr. Roger D. Walker, Director
Division of Project and Resident Programs
- Mr. Edward J. Butcher, Acting Chief
Operating Reactors Branch No. 3
Division of Licensing
- Mr. M. W. Branch
NRC Resident Inspector
North Anna Power Station

8511040419 851021
PDR ADOCK 05000338
Q PDR

1/0 IEOI