Ms. Irene M. Johnson, Acting Manager Nuclear Regulatory Services Commonwealth Edison Company Executive Towers West III 1400 Opus Place, Suite 500 Downers Grove, IL 60515

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION REGARDING SECOND 10-YEAR

INSERVICE INSPECTION PROGRAM - BYRON STATION (TAC NOS. M94830 AND

M94831)

Dear Ms. Johnson:

On February 23, 1996, Commonwealth Edison Company (ComEd) submitted its second linear Inservice Inspection (ISI) program and associated relief requests. In 25 submittal, ComEd requested expedited review for Relief Requests 12R-11 and 12R-12. Relief Request 12R-11 was subsequently withdrawn by ComEd on June 12, 1996; we authorized Relief Request 12R-12 on July 22, 1996.

Requests for Additional Information (RAI) were issued on June 13, 1996, October 16, 1996, and December 13, 1996. ComEd provided its response to the first RAI on August 12, 1996, and its response to the second and third RAIs on December 16, 1996. During the continuation of our review, we have identified the need for further information as discussed in the enclosed RAI. Please provide your response to the questions within 60 days of receipt of this request.

Sincerely,

ORIGINAL SIGNED BY: George F. Dick, Jr., Project Manager Project Directorate III-2 Division of Reactor Projects - III/IV Office of Nuclear Reactor Regulation

OFOIT

Docket Nos. STN 50-454, STN 50-455

Enclosure: RAI

cc w/encl: See next page

Distribution:

Docket File PUBLIC

PDIII-2 r/f
E. Adensam, EGA1
G. Dick, GFD
OGC, 015B18

J. Roe, JWR
R. Capra, FAC1
C. Moore, ACM
ACRS, T2E26

R. Lanksbury, RIII R. Wessman, 07E23

F. Grubelich, 07E23

040041

DOCUMENT NAME: BYRON\BY94830, RAI

To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

OFFICE	PM: PDIII-2 1	E LA: PDI 1-2	EMEB -	PD:PDIII-2 C	A
NAME	G. DICK VI	O_MOORE	R. WESSMAN	R. CAPRA pa	
DATE	01/29/97	01/7997	01750/97	01/30/97	

AFFICIAL RECORD COPY



UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

January 30, 1997

Ms. Irene M. Johnson, Acting Manager Nuclear Regulatory Services Commonwealth Edison Company Executive Towers West III 1400 Opus Place, Suite 500 Downers Grove, IL 60515

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION REGARDING SECOND 10-YEAR

INSERVICE INSPECTION PROGRAM - BYRON STATION (TAC NOS. M94830 AND

M94831)

Dear Ms. Johnson:

On February 23, 1996, Commonwealth Edison Company (ComEd) submitted its second 10-year Inservice Inspection (ISI) program and associated relief requests. In its submittal, ComEd requested expedited review for Relief Requests 12R-11 and 12R-12. Relief Request 12R-11 was subsequently withdrawn by ComEd on June 12, 1996; we authorized Relief Request 12R-12 on July 22, 1996.

Requests for Additional Information (RAI) were issued on June 13, 1996. October 16, 1996, and December 13, 1996. ComEd provided its response to the first RAI on August 12, 1996, and its response to the second and third RAIs on December 16, 1996. During the continuation of our review, we have identified the need for further information as discussed in the enclosed RAI. Please provide your response to the questions within 60 days of receipt of this request.

Sincerely.

George F. Nick, Jr. / Project Manager

Project Directorate III-2

Division of Reactor Projects - III/IV Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455

Enclosure: RAI

cc w/encl: See next page

I. Johnson Commonwealth Edison Company

cc:

Michael I. Miller, Esquire Sidley and Austin One First National Plaza Chicago, Illinois 60603

Regional Administrator, Region III U.S. Nuclear Regulatory Commission 801 Warrenville Road Lisle, Illinois 60532-4351

Illinois Department of Nuclear Safety Office of Nuclear Facility Safety 1035 Outer Park Drive Springfield, Illinois 62704

Document Control Desk-Licensing Commonwealth Edison Company 1400 Opus Place, Suite 400 Downers Grove, Illinois 60515

Mr. William P. Poirier, Director Westinghouse Electric Corporation Energy Systems Business Unit Post Office Box 355, Bay 236 West Pittsburgh, Pennsylvania 15230

Joseph Gallo Gallo & Ross 1250 Eye St., N.W. Suite 302 Washington, DC 20005

Howard A. Learner
Environmental law and Policy
Center of the Midwest
203 North LaSalle Street
Suite 1390
Chicago, Illinois 60601

U.S. Nuclear Regulatory Commission Byron Resident Inspectors Office 4448 North German Church Road Byron, Illinois 61010-9750

Ms. Lorraine Creek Rt. 1, Box 182 Manteno, Illinois 60950 Byron Station Unit Nos. 1 and 2

Chairman, Ogle County Board Post Office Box 357 Oregon, Illinois 61061

Mrs. Phillip B. Johnson 1907 Stratford Lane Rockford, Illinois 61107

Attorney General 500 South Second Street Springfield, Illinois 62701

EIS Review Coordinator
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Chicago, Illinois 60604-3590

Commonwealth Edison Company Byron Station Manager 4450 North German Church Road Byron, Illinois 61010

Kenneth Graesser, Site Vice President Byron Station Commonwealth Edison Station 4450 N. German Church Road Byron, Illinois 61010

REQUEST FOR ADDITIONAL INFORMATION SECOND 10-YEAR INSERVICE INSPECTION INTERVAL COMMONWEALTH EDISON COMPANY BYRON STATION, UNITS 1 AND 2 DOCKET NOS. STN 50-454 AND STN 50-455

The following questions pertain to Relief Request 12R-13.

- 1. The requirements of OMa-1988, Part 4, Section 2, per IWF-5200 pertain to preservice (pre-operational) examination of snubbers. In Relief Request 12R-13, the licensee states that similar requirements are included in the technical specifications (TS). Please identify the TS location for these requirements and describe their similarity with Part 4, Section 2 requirements or modify the relief request accordingly.
- 2. IWF-5400 requirements defer to OMa-1988, Part 4, and IWF-4000 for repair and IWF-7000 for the replacement of snubbers. The Byron relief request states that the repair and replacement requirements of IWF-4000 and 7000 will be met and snubber repair and replacement will be performed per the TSs in lieu of OMa-1988, Part 4, requirements. Please identify the TS location(s) that defines these requirements and describe how they replace the OMa-1988, Part 4, requirements.