


Substituted Pages
TMIA Ex #10

D-6 (Keaten -1)

R W Keaten

From 2/15/79 To 1/24/80



NUCLEAR REGULATORY COMMISSION

Docket No. _____ Official Exh. No. 10
In the matter of T.M.E.
Staff _____ IDENTIFIED ☒
Applicant _____ RECEIVED ☒
Intervenor _____ REJECTED ☐
Cont'g Off'r _____
Contractor _____ DATE 1-3-85
Other _____ Witness _____
Reporter J.W.

Steno
Notebook

80 SHEETS EYE-EASE® PAPER • GREGG RULED

BOOK NO. _____ FROM Feb 15 79 TO _____

NATIONAL BLANK BOOK COMPANY, INC. • HOLYOKE, MA. 01040



36-746
Made in USA

TMIA Exhibit 10

2 modified pages (Official stipulated copy)

8508200069 850103
PDR ADOCK 05000289
G PDR

① ID at 10⁴⁵ Airport TGB last 3/21/77
3/30
in red in red

② 1st Senators - briefing

③ S.C.E.

Cridermont Pump Trip - electrical ^{disturbance}
Train C-2 BFP Trip - Loss of P.W.
Turbine Trip.

7 sec - ΔP primary - ground E.M. - no indication that ^{it} _{is} ^{the} _{first}
9 sec - Surge H.P. (expected)

Looked normal w/ 1 min of pressure
P.W. did not stabilize out - continued to
may have been EM valve leak

2nd - 2 hr ^{1st} min H.P.T.

Pressure level up but pressure dropped still
Type - 5th (ck) rise constant or
slightly increasing - pressure increase
→ 4th min - P at point HL ^{in panel}
Pressure level ^{was} ~~to~~ trip, surge H.P.T.
level still increased started
to let down Pressure of 1.5 min
for 4th min.
Nucleon got rid of bubble
Bubble degraded pump performance (oscillation
(100-60%) - shut off pump. Closed order to
adjust valve.

is min
Pressure level
TH & TC
resing due
to the
heat
removal
H.P.T.
seconds
no 5th

Present status

Bubble in reactor

Non-convertibles in Breuniger

- lots -

Explosion in containment

1000 ft 3 @ 1000 psi

Could be 100,000 ft

light diagonal
from north through
8 and 0

(280) F 260-
250

Ed Wallace

(1) Century Supply / Sheraton 2-day:
Louisiana Smith

Need data

944-4041 X 319, 284, 385

Unit

(2) Century call Ted Meyer at Tokyo Ed.
Dicks in Sept 77 trip - send
to Ed at M.I.