

NOTICE OF VIOLATION

Ozark Environmental Laboratories,
Incorporated

License No. 24-20371-01

As a result of the inspection conducted on April 1, 1986, and in accordance with the "General Policy and Procedures for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1985), the following violations were identified:

1. License Condition 12 states that licensed material shall be used by, or under the supervision and in the physical presence of individuals who have satisfactorily completed the device manufacturers training program for gauge users.

Contrary to the above, licensed material was not used by, or under the supervision and in the physical presence of individuals who satisfactorily completed the device manufacturers training program for gauge users. For example, an unauthorized individual used the moisture/density gauge about seventy times between September 1985 and March 1986. The gauge was not used in the physical presence of an authorized individual.

This is a Severity Level IV violation (Supplement VI).

2. License Condition 17 requires that all licensed material be possessed and used in accordance with statements representations and procedures contained in application received April 14, 1983.

Application received April 14, 1983, states that the permanent storage location for nuclear gauges shall be located at 1306 Bishop Avenue, Rolla, Missouri.

Contrary to the above, the permanent storage location for nuclear gauges was not located at 1306 Bishop Avenue, Rolla, Missouri. Specifically, the permanent storage location was moved to 1511 Watts Drive, Rolla, Missouri. The permanent storage location was changed in June or July 1984.

This is a Severity Level IV violation (Supplement VI).

3. License Condition 13A states that each sealed source containing licensed material shall be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, each sealed source containing licensed material was not tested for leakage and/or contamination every six months. For example, the sealed sources were not tested for leakage in July 1985, and January 1986. This last test for leakage had been performed on January 18, 1985.

This is a Severity Level IV violation (Supplement VI).


Notice of Violation

2

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

4/18/86


D. J. Sreniawski, Chief
Nuclear Materials Safety
Section 2