

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	A	R	S	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5					
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										23	24	LICENSE TYPE					30	37	CAT	50			51

CON'T

REPORT SOURCE: L 6 0 5 0 0 0 3 1 1 2 7 0 9 1 1 3 7 1 8 8 1 0 0 5 7 1 8 9

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

BUCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During start tests following maintenance, P-996, the Diesel Driven Fire

03 Pump, tripped on overspeed. An investigation revealed the engine to pump

04 coupling bolts had sheared. Contrary to T.S., only one high pressure

[05] pump was available at that time. The redundant motor-driven pump, P-440.

06 was available at all times during the occurrence.

07

08

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 0 9 A B (11) B (12) C (13) M E C F U N (14) Z (15) Z (16)

LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
17		7 8		10 19		13		1		1	
21		22		24		26		27		28	
29		30		31		32		33		34	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED	
A		18		Z		Z		0 0 0 0		Y	
33		34		35		36		37		38	
39		40		41		42		43		44	
45		46		47		48		49		50	
51		52		53		54		55		56	
57		58		59		60		61		62	
63		64		65		66		67		68	
69		70		71		72		73		74	
75		76		77		78		79		80	
81		82		83		84		85		86	
87		88		89		90		91		92	
93		94		95		96		97		98	
99		100		101		102		103		104	
105		106		107		108		109		110	
111		112		113		114		115		116	
117		118		119		120		121		122	
123		124		125		126		127		128	
129		130		131		132		133		134	
135		136		137		138		139		140	
141		142		143		144		145		146	
147		148		149		150		151		152	
153		154		155		156		157		158	
159		160		161		162		163		164	
165		166		167		168		169		170	
171		172		173		174		175		176	
177		178		179		180		181		182	
183		184		185		186		187		188	
189		190		191		192		193		194	
195		196		197		198		199		200	
201		202		203		204		205		206	
207		208		209		210		211		212	
213		214		215		216		217		218	
219		220		221		222		223		224	
225		226		227		228		229		230	
231		232		233		234		235		236	
237		238		239		240		241		242	
243		244		245		246		247		248	
249		250		251		252		253		254	
255		256		257		258		259		260	
261		262		263		264		265		266	
267		268		269		270		271		272	
273		274		275		276		277		278	
279		280		281		282		283		284	
285		286		287		288		289		290	
291		292		293		294		295		296	
297		298		299		300		301		302	
303		304		305		306		307		308	
309		310		311							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The probable cause was overtightening of the coupling bolts during initial

11 installation. The bolts were replaced, proper alignment verified, and the

1 2 torque values on replacement bolts verified to not exceed recommended

13 value.

1 d

FACILITY STATUS		% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION							
1	5	E	35	1	0	0	30	NA	B	31	Maintenance Testing	32

8 9		10		12		13		44		45		46		80	
ACTIVITY				CONTENT											
RELEASED				OF RELEASE				AMOUNT OF ACTIVITY (35)				LOCATION OF RELEASE (36)			
1	6	Z	(33)	Z	(34)	NA				NA					

PERSONNEL EXPOSURES		44		45		80	
NUMBER	TYPE	DESCRIPTION					
17	0001Z	NA					

PERSONNEL INJURY		ES		DESCRIPTION		NA	
NUMBER							
1	0	0	0	4			

6	9	11	12		80
LOSS OF OR DAMAGE TO FACILITY (43)					
TYPE		DESCRIPTION			
1	9	Z	(42)	NA	

ISSUED 20 Y 34 45 Local newspaper and wire service 9-21-78

NRC USE ONLY

NAME OF PREPARER R. W. Colombo

PHONE: (916)⁶⁸⁶⁹ 452-3211

7810130190