McCALLUM TESTING I ABORATORIES Subsurface Exploration • Geotechnical Engineering

January 18, 1988

Nuclear Regulatory Commission Washington, DC 20555

Attention: Document Control Desk

Subject: Reply to a Notice of Violation Docket #030-08916 License No. 45-15325-01

To Whom It May Concern:

This letter is in response to the violations as noted by Ms. S. Waldron on December 9, 1987.

In regards to Violation "A", McCallum Testing Laboratories, Inc. admits in failing to regular leak test every six months as required. We feel the tests were not completed as required because of inadequate record keeping. Since our inspection, we have leak tested every unit, set up individual files for each unit and we have assigned one individual to oversee this particular area of operation. We were in compliance as of December 17, 1987.

In regards to Violation "B" we again admit to the subject violation. It was an unfortunate oversight on our part. Since that inspection we have posted all required material on a bulletin board in a common area available to all employees. We were in compliance as of December 12, 1987.

We apologize for these violations and rest assured we will do everything in our power to see that we stay in compliance as required by our license.

If you need anything further, please feel free to call.

Yours truly,

McCALLUM TESTING LABORATORIES, INC.

Philip S. Berman Radiation Safety Officer

(804) 420-2520

8801220063 880118 NMSS LIC30 45-15325-01 DC 1808 HAYWARD AVENUE

DCD

P.O. BOX 13266

CHESAPEAKE, VIRGINIA 23325

McCALLUM TESTING LABORATORIES Subsurface Exploration • Geotechnical Engineering

January 18, 1988

Nuclear Regulatory Commission Washington, DC 20555

Attention: Document Control Desk

Subject: Reply to a Notice of Violation Docket #030-08916 License No. 45-15325-01

To Whom It May Concern:

This letter is in response to the violations as noted by Ms. S. Waldron on December 9, 1987.

In regards to Violation "A", McCallum Testing Laboratories, Inc. admits in failing to regular leak test every six months as required. We feel the tests were not completed as required because of inadequate record keeping. Since our inspection, we have leak tested every unit, set up individual files for each unit and we have assigned one individual to oversee this particular area of operation. We were in compliance as of December 17, 1987.

In regards to Violation "B" we again admit to the subject violation. It was an unfortunate oversight on our part. Since that inspection we have posted all required material on a bulletin board in a common area available to all employees. We were in compliance as of December 12, 1987.

We apologize for these violations and rest assured we will do everything in our power to see that we stay in compliance as required by our license.

If you need anything further, please feel free to call.

Yours truly,

McCALLUM TESTING LABORATORIES, INC.

lo A Brow

Philip S. Berman Radiation Safety Officer

1808 HAYWARD AVENUE

P.O. BOX 13266

CHESAPEAKE, VIRGINIA 23325

(804) 420-2520