



Log # TXX-88244
File # 10110
903.9
Ref. # 10CFR50.55(e)

March 30, 1988

William G. Council
Executive Vice President

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
CABLE TRAY CLAMPS
SDAR CP-83-15 (SUPPLEMENTAL REPORT)

Gentlemen:

On July 12, 1983, in our report logged TXX-4005, we notified you of a deficiency involving the bolting material used for cable tray clamps which we deemed reportable under the provisions of 10CFR50.55(e). This item was subsequently identified by our report logged TXX-6435, dated May 13, 1987, as an item for which a final report had been issued but, the corrective actions require revision. This report is submitted to status the implementation of those corrective actions.

On September 6, 1985, we verbally notified your Mr. C. Gould of a deficiency, SDAR CP-85-35, "Cable Tray Hanger Design," involving the design and construction activities of the cable tray hanger program. This issue, SDAR CP-85-35, was subsequently determined to be reportable under the provisions of 10CFR50.55(e) by our report logged TXX-6048, dated October 21, 1986. The issue regarding inadequate bolting material and fastener tension for cable tray clamps (SDAR CP-83-15) will be resolved and reported under the corrective action program for SDAR CP-85-35. Our next report for SDAR CP-85-35 will be submitted by April 27, 1988.

This is our final report for SDAR CP-83-15.

Very truly yours,

W. G. Council
W. G. Council

CBC/grr

c - Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

JE27
10