SAFETY INSPECTION

DMB COPY

1. LICENSEE

Ricerca, Inc. (SDS Biotech Corp.) P. O. Box 1000 Painesville, Ohio 44077 2. REGIONAL OFFICE

U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT RD. GLEN ELLYN, IL 60137

3. DOCKET NUMBER(S) | 4. LICENSE NUMBER(S) | 5. DATE OF INSPECTION

	The state of the s	
Licensee:		
Regulatory Commission's (NRC) rules and regula		pradiation safety and to compliance with the Nuclear pection consisted of selective examinations of procedures dings as a result of this inspection are as follows:
1. Within the scope of this inspection, no vid	plations were observed.	
The inspector also verified the steps you those actions at this time.	have taken to correct the violations identified duri	ing the last inspection. We have no further questions on
	livities, as checked below, were in violation of NRI nich is required to be posted in accordance with 10	
		was not properly posted to indicate the presence . 10 CFR 20.203(b), (c), (d), (e) or 34.42.
B. Containers located in		were not properly
labeled to indicate the presence of rad	floactive material. 10 CFR 20.203(f)(1), or (f)(2).	
		of sealed sources were not performed at the proper
frequencies. 10 CFR	Lice	ense Condition Number
D. Records of Area Survey	s in the LS-122 Laborato	/ 0 / - 1
10074	AF AUTOB DANKE	MARIAN (-04 DICCHSO)
E. Documents were not properly posted	or otherwise made available. 10 CFR 19.11.	
F. Reports or notifications of	or License Condition	were not made in accordance
x H. A Texas Nuclear 2	650 survey instrument wa	s not calibrated semiannually
as required by Li	cense Condition No. 22 (-04 license).
-		
J	-70114	
8802020374 REG3 LIC30	8/0114	
34-00583-0	4 PDR	
N. Harrison		

the NRC.