

Appendix A

NOTICE OF VIOLATION

American Electric Power  
Service Corporation  
Indiana and Michigan  
Power Company

Docket No. 50-316

Based on the inspection conducted on August 28-31, September 1, 11-15, 18, 20-22, 25-29, October 2 and 4-6, 1978, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. These items are considered to be infractions.

- A. Technical Specification 6.8.1 requires procedures be implemented. PMI-2140, "Bypass of Safety Functions; Jumpers, Grounds, Lifted Wire and Blocked Relay Control" requires alarms which are blocked be approved and logged.

Contrary to the above, on August 29, 1978, the Unit 2 RWST piping for low temperature alarm was blocked without being approved and logged.

- B. Technical Specification 6.8.1 requires procedures be implemented. PMI-7030, "Condition Reports" requires that condition reports be promptly initiated for events which may be reportable to external organizations.

Contrary to this requirement, Condition Reports were not promptly initiated for the inoperability of the Unit 2 AB diesel generator on June 14, 1978 and the opening of Unit 2 ice condenser doors on September 26, 1978.

7812130037