

JAN 8 1988

Docket No. 50-454
Docket No. 50-455

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Senior Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. W. B. Grant and W. W. Ogg of this office on December 8-11, 1987, of activities at Byron Nuclear Power Station, Units 1 and 2, authorized by NRC Operating Licenses No. NPF-37 and No. NPF-66 and to the discussion of our findings with Mr. R. Ward and others at the conclusion of the inspection.


The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,


W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosure: Inspection Reports
No. 50-454/87044(DRSS);
No. 50-455/87042(DRSS)

See Attached Distribution

RIII
wsb
Grant/abl

RIII
WWD
Ogg

RIII
AKG
Greger

⁴
RIII
[Signature]
Hinds

RIII
AKG
Shafer

IEDG

11

2 JAN 8 1989

Distribution

cc w/enclosure:

T. J. Maiman, Vice President,
PWR Operations

D. Butterfield, Nuclear
Licensing Manager

R. E. Querio, Plant Manager
DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII Byron

Resident Inspector, RIII

Braidwood

D. W. Cassel, Jr., Esq.

Richard Hubbard

J. W. McCaffrey, Chief, Public
Utilities Division

Diane Chavez, DAARE/SAFE

L. Olshan, NRR LPM

H. S. Taylor, Quality Assurance
Division