## **Citizens Urging Responsible Energy**

P. 02

September 16, 1994

.. .. 4

Ivan Selin, Chairman US Nuclear Regulatory Commission Washington, D.C. 20555

Via Fax: (301) 504-1672

Dear Chairman Selin:

As you are avere, the Pilgrim Nuclear Power Station automatically shutdown on August 29, 1994. This is the fourth unplanned shutdown this year. While various malfunctions associated with the shutdown remain under investigation, it is now apparent that the plant's main generator was seriously damaged. Boston Edison originally said there was "no damage to any of the equipment." However, at a press conference last Monday, the company confirmed that Pilgrim will remain off line for up to four months to complete up to \$6 million in repairs.

Our purpose in writing is to inform you that two anonymous sources have stated that Boston Edison is aware that the core shroud at Pilgrim is cracked. Have you been noticed of such findings, or has past NRC inspection activity identified any core shroud crack indications at Pilgrim?

Clearly the NRC views the subject of core shroud cracking with great concern since you have issued Generic Letter 94-03, "Intergranular Stress Corros on Cracking (IGSSC) of Core Shrouds in Boiling Water Reactors," on July 25, 1994 with no notice of opportunity for public comment "because of the urgent nature of the actions requested." In fact, Pederal Register, Volume 59, No. 155/ Friday, August 12, 1994 says, "The NRC determined that the need for licensees to implement the requested actions quickly made it necessary to issue this generic letter immediately."

In view of Pilgrim's unexpected lengthy outage and the emergent nature of this issue, we feel it would be prudent for the NRC to move up the schedule for Pilgrim's core shroud inspection. Have you considered this action?

9411040284

Finally, the NRC's "WEEKLY INFORMATION REPORT" to you for week ending July 15, 1994 notices an August 4, 1994 meeting with Boston Edison "To discuss the reactor vessel inspection scheduled for the April 1995 refueling outage and (an) IOSCC inspection relief request." Please provide us with a copy of the company's request and the current status of this issue. We would also like to know what criteria, standarde or regulations the NRC will use in deciding whether to grant the requested relief.

We look forward to your reply.

Sincerely yours,

Janeld Mr. Mundeal Mary C. Ott

£ 1 +

P.02

CCI

Senator Edward Kennedy Senator John Kerry / Congressman Gerry Studds Attorney General Scott Earshbarger Ronald Eaton Robert Pollard

## CONGRESSIONAL CORRESPONDENCE SYSTEM DOCUMENT PREPARATION CHECKLIST

-----

1 ,

04/	s checklist is be submitted with each document (or group of As) sent for . ing into the GLT.
1.	BRIZE DESCRIPTION OF DOCUMENT(S) 44 4 Lep Sudde
	TIPE OF DOCUMENT COTTESPONDENSE TESTINGE (05/20)
3.	DOC VENT CONTROL Sensitive (LAC Only) Non-Sensitive
4.	CONGRESSIONAL COMMITTEE and SUBCOMMITTEEs (if applicable)
	Congressional Committee
-	Subcommittee
з.	SUBJECT CODES
	(2)
	(b)
6.	SOURCE OF DOCUMENTS
	(a) 5520 (document name
	(b) Scan- (c) Attachments
	(d) Rekay (e) Other
7.	SYSTEM LOG LATES
	(a) Dats OCL sent document to CCS
	(b) Data CCS. racaives document
	(c) Date returned to OCA for additional information
	(d) Date resubmitted by och to ccs
	(a) Data entared into CCS by
	(f) Data OCA notified that document is in CCS
8	(1) ういのと、 第一部では、 第二部では、 11 **: **: **: **: **: **: **: **: **: