



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
811 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

~~1. GWO~~
2. EAT

78-13
303

August 25, 1978

In Reply Refer To:

RIV

Docket No. 50-498/Rpt. 78-13
50-499/Rpt. 78-13

ST-AE-HL-566

RECEIVED SFN: C-0570

AUG 28 1978

E. A. TURNER

Habacck
38

Houston Lighting and Power Company
ATTN: Mr. E. A. Turner, Vice President
Power Plant Construction and
Technical Services

Post Office Box 1700
Houston, Texas 77001

Gentlemen:

This refers to the meeting held by representatives of the Office of Inspection and Enforcement staff, Region IV, with you and members of your staff on August 15, 1978, regarding your activities authorized by NRC Construction Permit Nos. CPPR-128 and 129 for South Texas Project, Units No. 1 and 2.

The attached report documents the topics discussed at this meeting.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed report will be placed in the NRC's Public Document Room. If the report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office, within 20 days of the date of this letter, requesting that such information be withheld from public disclosure. The application must include a full statement of the reasons why it is claimed that the information is proprietary. The application should be prepared so that any proprietary information identified is contained in an enclosure to the application, since the application without the enclosure will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

7809270378
2PP

F-836


Houston Lighting & Power Co.

-2-

August 25, 1978

Should you have any questions concerning this meeting, we will be pleased to discuss them with you.

Sincerely,



W. C. Seidle, Chief
Reactor Construction and
Engineering Support Branch

Enclosure:

IE Inspection Report No. 50-498/78-13
50-499/78-13