

APPENDIX

SALP 7

SALP BOARD REPORT

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE

50-454/88001; 50-455/88001
Inspection Report No.

Commonwealth Edison Company
Name of Licensee

Byron Station
Name of Facility

November 1, 1986 through October 31, 1987
Assessment Period

8803210015 880311
PDR ADOCK 05000454
Q JCD

A. Summary of Meeting with Commonwealth Edison Company on January 29, 1988

The findings and conclusions of the SALP Board documented in Inspection Report Nos. 50-454/88001; 50-455/88001 were discussed with the licensee on January 29, 1988, at the Byron Station Training Building. The licensee's regulatory performance was presented and found acceptable in each functional area.

The following individuals attended the meeting:

Commonwealth Edison Company

B. L. Thomas, President
C. Reed, Senior Vice President
T. J. Maiman, Vice President, PWR Operations
K. L. Graesser, General Manager, PWRs
R. E. Querio, Byron Station Manager
E. E. Fitzpatrick, Braidwood Station Manager
R. Pleniewicz, Production Superintendent, Byron
R. Lucas, Byron Security Administrator
A. J. Chernick, Training Supervisor, Byron
T. K. Higgins, Operating Engineer, Byron
G. K. Schwartz, Assistant Superintendent, Maintenance, Byron
L. A. Sues, Assistant Superintendent, Technical Services, Byron
W. Burkamper, Quality Assurance Superintendent, Byron
H. P. Studtmann, Director of Quality Assurance (Maintenance)
R. W. Stobert, Director of Quality Assurance (Operations)
P. J. Nodzinski, PWR Engineering, Byron Station
D. Elias, PWR Engineering Superintendent
W. P. Dijstelbergen, PWR Byron Field Engineering Supervisor
E. Zittle, Byron Regulatory Assurance
R. Curtis, Training Department, Byron
L. C. Bird, Project Construction Services Department
G. Sorensen, Construction Superintendent, Byron
W. Benjamin, Nuclear Safety Department
W. J. Dean, Byron On-Site Nuclear Safety
T. P. Joyce, Assistant Superintendent, Operations
W. D. Pirnat, Byron Regulatory Assurance
D. St. Clair, Assistant Superintendent, Work Planning
F. Lentine, PWR Licensing Supervisor
K. Ainger, Nuclear Licensing Administrator
P. Barnes, Braidwood Regulatory Assurance Supervisor
T. McIntire, Division Superintendent

Public

E. Hinton, Oregon Republican
D. Gertz, Freeport Journal Standard
S. McKinley, WTVQ-TV
M. Magliari, WNIU

L. Green, Rockford Register Star
S. Campbell, Mississippi Alliance for the Environment
P. Gluntz, Dixon Telegraph
D. Chavez, Mississippi Alliance for the Environment
L. Johnson, WIFR-TV
L. J. Jarrett, WIFR-TV

State Government Agencies

R. Hallin, Illinois Emergency Services and Disaster Agency

U. S. Nuclear Regulatory Commission

A. Bert Davis, Regional Administrator
W. L. Forney, Chief, Reactor Projects Branch 1
J. M. Hinds, Jr., Chief, Reactor Projects Section 1A
L. N. Olshan, LPM, Byron
P. G. Brochman, Senior Resident Inspector, Byron
N. V. Gilles, Resident Inspector, Byron
G. A. VanSickle, Project Inspector, Section 1A
W. Newmyer, Region III Engineering Aide

B. Comments Received from Licensee

By letter dated February 29, 1988, the licensee provided a written response to the SALP Report in accordance with the forwarding letter. The licensee's response briefly states that plant housekeeping could have received greater recognition in the report and that programs are in place to address the identified concern with personnel errors at the station.

As the licensee's response provides no comments addressing the specific content of the report, this Appendix contains no changes to the SALP Report.

C. Regional Administrator's Conclusions Based on Consideration of Licensee Comments

Byron's overall ratings in the affected areas have not changed.