



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

JUL 08 1988

Docket No. 50-454

Docket No. 50-455

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Senior Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:

Your letters of May 15 and August 28, 1986, and April 24 and November 24, 1987, pertaining to Byron, contained your response to IEB 85-03, "Motor-Operated Valve Common Mode Failures During Plant Transients Due to Improper Switch Settings". The review of these responses led to the issuance of a request for additional information on March 21, 1988, and response by you on May 2, 1988. Review of this additional information indicates that your selection of the applicable safety-related valves, the valves' maximum differential pressures and your program to assure valve operability requested by action item e. of the bulletin is now acceptable.

The results of our inspections to verify proper implementation of this program and the review of the final response required by action item f. of the bulletin will be addressed in forthcoming inspection reports.

A handwritten signature in cursive script, appearing to read "Edward G. Greenman".

Edward G. Greenman, Director
Division of Reactor Projects

See Attached Distribution

IE11
10

JUL 08 1988

Distribution

cc: T. J. Maiman, Vice President,
PWR Operations
H. Bliss, Nuclear
Licensing Manager
R. Pleniewicz, Station Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII Byron
Resident Inspector, RIII
Braidwood
D. W. Cassel, Jr., Esq.
Richard Hubbard
J. W. McCaffrey, Chief, Public
Utilities Division
Diane Chavez, DAARE/SAFE
L. Olshan, NRR LPM
H. S. Taylor, Quality Assurance
Division
R. J. Kiessel, NRR
L. N. Olshan, NRR