

DUKE POWER

September 1, 1988

Document Control Desk U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Subject: Catawba Nuclear Station Docket No. 50-413 Special Report

Gentlemen:

Pursuant to Technical Specifications 3/4.4.5.5(a) and 6.9.2 attached is a Special Report concerning the plugging of 2 tubes in Steam Generator '1D' on August 18, 1988.

Very truly yours,

Hall Tucker

Hal B. Tucker

PGL/

Attachment

xc: Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Mr. P. K. Van Doorn NRC Resident Inspector Catawba Nuclear Station

8809070402 880901 PDR ADOCK 05000413 PNU IEZZ

CATAWBA NUCLEAR STATION, UNIT 1

PLUGGING OF 2 TUBES IN STEAM GENERATOR '10'

On August 18, 1988, 2 tubes in Steam Generator (S/G) 1D were plugged. Tubes 1-53 and 1-8 were plugged. Pluggable indications were found on these tubes in the U-bend transition region. The probable cause of the indications is the stress from the tight U-bends. The indications were not caused by problems identified in NRC Bulletin 88-02. At the time Unit 1 was shutdown to repair the tubes, Reactor Coolant System leakage was well below the leakage allowed by Technical Specification 3.4.6.2.