

Commonwealth Edison Company
Braidwood Generating Station
Route #1, Box 84
Braceville, IL 60407-9619
Tel 815-458-2801



October 2, 1998

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

The enclosed Licensee Event Report (LER) from Braidwood Generating Station is being transmitted in accordance with 10 CFR 50.73(a)(2)(I)(B), which requires a 30 day report.

The following commitments were made in this LER:

- The disc from one of the failed Main Steam Safety Valves (MSSVs), 1MS016B, will be evaluated.
- A review of past MSSV rebuild work packages, procedure revisions, and differences between Braidwood and Byron MSSV maintenance practices will be conducted to assess whether these factors could have contributed to the MSSV test failures.
- A supplement to this LER is expected to be submitted by June 28, 1999, following an evaluation of the investigation results and other industry developments.

If your staff has any questions or comments concerning this LER, please refer them to Terrence Simpkin, Braidwood Regulatory Assurance Supervisor, at (815) 458-2801, extension 2980.

Timothy J. Tulong
Site Vice President
Braidwood Nuclear Generating Station

Attachment

cc: C. J. Paperiello, Acting NRC Regional Administrator, Region III
C. J. Phillips, Senior Resident Inspector
F. Niziolek, Division of Engineering, Office of Nuclear Safety, IDNS
INPO Record Center

TE2211

nrc/98064tjt.doc

9810060006 981002
PDR ADOCK 05000456
S PDR