

Douglas R. Gipson
Senior Vice President, Nuclear Generation

Fermi 2
6400 North Dixie Hwy., Newport, Michigan 48166
Tel: 313.586.5201 Fax: 313.586.4172

Detroit Edison



10CFR50.73

October 1, 1998
NRC-98-0113

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Reference: Fermi - 2
NRC Docket No. 50-341
NRC License No. NPF-43

Subject: Licensee Event Report (LER) No. 98-005

Pursuant to 10CFR50.73, Detroit Edison Company is submitting the enclosed LER No. 98-005 documenting an unplanned manual reactor scram in response to reactor power fluctuations.

The following commitment is being made in this LER:

- Problems identified during the Sixth Refueling Outage (RFO6) High Pressure Turbine Control Valve (HPTCV), Turbine Stop Valve (TSV), and Turbine Bypass Valve (TBPV) work activities will be investigated and resolved prior to reactor startup from RFO6.

If you have any questions, please contact Norman K. Peterson, Director Nuclear Licensing at (734) 586-4258.

Sincerely,

9810060142 981001
PDR ADOCK 05000341
S PDR

cc: Regional Administrator, Region III
B. L. Burgess
G. A. Harris
A. J. Kugler
M. V. Yudas, Jr.
Region III
Wayne County Emergency Management Division

0500039

IE22/1