Docket No. 50-346

License No. NeF-3

August 31, 1988

-C TOLEDO

EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652-0001

Log No. KA88-0286 NP-29-88-01

Mr. A. Bert Davis, Regional Administrator U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60317



Subject: Special Report of Inoperable Seismic Monitor System Due to Maintenance

Gentl men:

On July 22, 1988 with the reactor defueled the Seismic Monitoring System accelerometers were removed for calibration. However, the accelerometers could not be calibrated to acceptable standards. Since these accelerometers are obsolete, spare parts and direct replacements are not available. Subsequently, it was decided to replace the accelerometers with a new type under plant modification number 88-0060. Due to priority conflicts in the outage schedule, the modification was not implemented prior to August 21, 1988. This report is being submitted in accordance with Technical Specification 3.3.3.3 because the seismic monitoring system has been inoperable for more than 30 days.

This modification is scheduled for completion by September 15, 1988. This will return the seismic monitor system to an operable status.

Yours truly,

Louis F. Storz Plant Manager

Davis-Besse Nuclear Power Station

LFS/ed

cc: Mr. Paul Byron

DB-1 NRC Resident Inspector

USNRC Document Control Desk Washington, D. C. 20555

8809140397 880831 PDR ADOCK 05000346 S PDC and distribution 1 1988