September 30, 1998

Mr. John K. Wood Vice President - Nuclear Davis-Besse Nuclear Power Station Centerior Service Company 5501 North State Route 2 Oak Harbor, OH 43449

## SUBJECT: NRC RADIATION PROTECTION INSPECTION REPORT 50-346/98016(DRS)

Dear Mr. Wood:

On September 4, 1998, the NRC completed a routine inspection at your Davis-Besse Nuclear Power Station. The enclosed report summarizes the results of this inspection.

The inspection was an examination of activities conducted under your license as they relate to radiat on safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. Specifically, the inspection focused on the external exposure monitoring program, the calibration and test program for radiation monitoring equipment and the program for the control of materials for unconditional release from the radiologically restricted area (RRA). Also reviewed was the station's response to a June 24, 1998, condensate system resin intrusion incident; the radiological controls for a containment entry during power operations that occurred during the inspection period; and the as-low-as-is-reasonably-achievable (ALARA) program implemented for the eleventh refueling outage.

Overall, programs were effectively implemented. In particular, administrative controls were established to maintain worker exposure ALARA, and your staff continued to maintain good oversight of the dosimetry processor. Programs for the calibration and testing of radiation monitoring equipment and for the control of material for release from the RRA were also well implemented; however, some examples were identified where procedural improvement was necessary to ensure consistency with station practices and to clarify program implementation.

We also concluded that your staff's response to the resin intrusion incident was appropriate, and included increased management attention and coordination with vendor representatives to ensure recovery plans were technically sound.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

9810070147 980930 PDR ADOCK 05000346 J. Wood

2

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Origina 1Signed by Steven A. Reynolds (for) John A. Grobe, Director Division of Reactor Safety

Docket No.: 50-346 License No.: NPF-3

Enclosure: Inspection Report 50-346/98016(DRS)

cc w/encl:

J. Stetz, Senior Vice President - Nuclear J. Lash, Plant Manager J. Freels, Manager, Regulatory Affairs M. O'Reilly, FirstEnergy State Liaison Officer, State of Ohio R. Owen, Ohio Department of Health C. Glazer, State of Ohio Public Utilities Commission

Distribution:

Project Mgr., NRR w/encl J. Caldwell, RIII w/encl C. Pederson, RIII w/encl B. Clayton, RIII w/encl SRI Davis-Besse w/encl DRP w/encl TSS w/encl DRS (2) w/encl RIII PRR w/encl PUBLIC IE=01 w/encl Docket File w/encl GREENS IEO (E-Mail) DOCDESK (E-Mail)

## DOCUMENT NAME: G:DRS\DAV98016.WPD

OFFICE	RIII	RIII E	RIII	RIII IV
NAME	BLANDSHTJE DUL	Shear BLS	Kozak AFG	Grobe Sh
DATE	09/24/98	09/28/98	09/1%/98	09/30/98

OFFICIAL RECORD COPY

000010