

Paul Fessler, P.E.  
Assistant Vice President, Nuclear Operations

Fermi 2  
6400 North Dixie Hwy., Newport, MI 48166  
Tel: 734.586.5325

**Detroit Edison**



10CFR50.73

October 5, 1998  
NRC-98-0133

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

Reference: Fermi 2  
NRC Docket No. 50-341  
NRC License No. NPF-43

Subject: Licensee Event Report (LER) No. 98-007

Pursuant to 10CFR50.73(a)(2)(iv), Detroit Edison is hereby submitting the enclosed LER No. 98-007 which documents the inadvertent deenergization of safety buses 65E, 72E, 13EC, and 72EC when the EDG 13 output breaker opened during performance of surveillance testing. This deenergization resulted in several ESF actuations.

There are no commitments made in this LER. Please contact Norman K. Peterson at (734) 586-4258 if you have any questions.

Sincerely,

cc: Regional Administrator, Region III  
B. L. Burgess  
G. A. Harris  
A. J. Kugler  
M. V. Yudas, Jr.  
Region III  
Wayne County Emergency Management Division

||  
IE22.

9810090194 981005  
PDR ADOCK 05000341  
S PDR