

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-414  
 UNIT NAME CATAWBA 2  
 DATE 07/15/88  
 COMPLETED BY J. A. REAVIS  
 TELEPHONE (704)-373-7567

REPORT MONTH June 1988

Revision 1

N O	DATE	(1)	DURATION HOURS	(2)	(3)	LICENSE EVENT REPORT NO.	(4)	(5)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
		T Y P E		R E A S O N	MET- HOD OF SHUT DOWN R/X		SYS- TEM CODE	COMPONENT CODE	
62-p	88- 6-23	F	--	B	--		HJ	PUMPXX	POWER REDUCTION DUE TO '2C1' HEATER DRAIN PUMP LOOP CALIBRATION
15	88- 6-26	F	17.05	G	3		ZZ	HTEXCH	REACTOR TRIP DUE TO INADVERTANT CLOSING OF STEAM GENERATOR '2D' MAIN STEAM ISOLATION
63-p	88- 6-28	F	--	A	--		HE	TURBIN	HOLDING POWER DUE TO STEAM LEAK ON THE INLET LINE TO THE HIGH PRESSURE TURBINE
64-p	88- 6-28	F	--	A	--		HE	TURBIN	POWER REDUCTION TO REPAIR A STEAM LEAK ON THE INLET LINE TO THE HIGH PRESSURE TURBINE
65-P	88- 6-28	F	--	A	--		HE	TURBIN	HOLDING POWER TO REPAIR A STEAM LEAK ON THE INLET LINE TO THE HIGH PRESSURE TURBINE

- (1)  
 F Forced  
 S Scheduled
- (2)  
 Reason:  
 A-Equipment Failure (Explain)  
 B-Maintenance or test  
 C-Refueling  
 D-Regulatory Restriction  
 E-Operator Training & License Examination  
 F-Administrative  
 G-Operator Error (Explain)  
 H-Other (Explain)

- (3)  
 Method:  
 1-Manual  
 2-Manual Scram  
 3-Automatic Scram  
 4-Other (Explain)

- (4)  
 Exhibit G - Instructions for Preparation of Data Entry Sheets For License Event Report (LER) File (NUREG-0161)

- (5)  
 Exhibit I - Same Source