

Point Beach Nuclear Plant 6610 Nuclear Rd., Two Rivers, WI 54241

NPL 98-0796

(920) 755-2321

10 CFR 50.73

October 7, 1998

Document Control Desk U.S. NUCLEAR REGULATORY COMMISSION Mail Station P1-137 Washington, DC 20555

Ladies/Gentlemen:

DOCKETS 50-266 AND 50-301 LICENSEE EVENT REPORT 1998-003-01 CONTAINMENT ACCIDENT FAN MOTOR COOLER HEAT EXCHANGER FLOW RATES FOUND TO BE OUTSIDE THE DESIGN BASIS OF THE PLANT POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

Enclosed is Supplemental Licensee Event Report 1998-003-01 for Point Beach Nuclear Plant, Unit 1 and Unit 2. This report is provided in accordance with 10 CFR 50.73(a)(2)(ii)(B), "in a condition outside the design basis of the plant." This report describes the discovery that flow meters used to set service water flow through the accident fan cooler motor heat exchangers resulted in potentially less flow than that assumed in the analysis for the operability of the motors during an accident. This supplement to the original report is provided to revise our corrective action commitment concerning replacement of the service water piping to the Unit 2 fan cooler motor heat exchangers. All changes or additions to the original report have been identified with margin bars.

No new commitments are established within this supplemental report.

Please contact us if you require additional information.

Sincerely, A Kaminskas

Manager, Regulatory Services & Licensing

Enclosure

JJUST

cc: NRC Resident Inspector PSCW 9810130228 981007 5000266 ADOCK PDR

NRC Regional Administrator INPO Support Services

A subsidiary of Wisconsin Energy Corporation