Mr. Oliver D. Kingsley, President Nuclear Generation Group Commonwealth Edison Company Executive Towers West III 1400 Opus Place, Suite 500 Downers Grove, IL 60515

SUBJECT: EVALUATION OF COMMONWEALTH EDISON COMPANY RESPONSE TO NRC GENERIC LETTER 97-05 FOR BYRON STATION, UNITS 1 AND 2 AND BRAIDWOOD STATION, UNITS 1 AND 2 (TAC NOS. MA0447, MA0448, MA0449 AND MA0450)

Dear Mr. Kingsley:

On December 17, 1997, the NRC issued Generic Letter (GL) 97-05, "Steam Generator Tube Inspection Techniques." GL 97-05 required a response from licensees which addressed whether it is their practice to leave steam generator tubes with indications in service based on sizing, and if yes, to provide a written report that includes, for each type of indication, a description of the associated nondestructive examination method being used and the technical basis for the acceptability of the technique used. The focus of GL 97-05 was to verify that licensee steam generator tube inspection practices were consistent with existing regulatory requirements and plant licensing bases. By letter dated February 27, 1998, Commonwealth Edison Company submitted a response to this GL that included a description and technical basis for all inspection techniques used to size the depth of steam generator tube degradation at Byron Station, Units 1 and 2, and Braidwood Station, Units 1 and 2. The staff's review of your response did not identify any concerns with the steam generator tube inspection techniques employed at Byron or Braidwood that would indicate noncompliance with the current licensing basis for these facilities. This concludes our review of GL 97-05 for Byron Station, Units 1 and 2, and Braidwood Station, Units 1 and 2.

Sincerely,

ORIG. SIGNED BY
John B. Hickman, Project Manager
Project Directorate III-2
Division of Reactor Projects - III/IV
Office of Nuclear Reactor Regulation

DFOI

Docket Nos. STN 50-454, STN 50-455 STN 50-456 and STN 50-457

cc: See next page

DISTRIBUTION:

Docket File PUBLIC S. Richards PD3-2 r/f

LIC OGC, O-15B18 -2 r/f M. Jordan, RIII P. Rush S. Bailey

C. Moore

E. Adensam, EGA1

J. Hickman

DOCUMENT NAME: G:\CM\BRAID-BY\BB0449.LTR No changes to evaluation memo\*
To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No

To receive a copy of this document, Indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

SEE PREVIOUS CONCURRENCE\*

OFFICE	PM:PDIII-2	LA	PDIII-2	PM:PDIII-2 6	(A)C:EMCB*	D:PDIII-2
NAME	JHickman:so	MOM	obre of fa	SBailey SMS	ELMurphy	SRichards*
DATE	8/26/98	10/	6 /98	10/ 9 /98	08/04/98	10/01/98

OFFICIAL RECORD COPY

O. Kingsley Commonwealth Edison Company

CC:

Ms. C. Sue Hauser, Project Manager Westinghouse Electric Corporation Energy Systems Business Unit Post Office Box 355 Pittsburgh, Pennsylvania 15230

Joseph Gallo Gallo & Ross 1250 Eye St., N.W., Suite 302 Washington, DC 20005

Michael I. Miller, Esquire Sidley and Austin One First National Plaza Chicago, Illinois 60603

Howard A. Learner
Environmental law and Policy
Center of the Midwest
35 East Wacker Dr., Suite 1300
Chicago, Illinois 60601

U.S. Nuclear Regulatory Commission Byron Resident Inspectors Office 4448 N. German Church Road Byron, Illinois 61010-9750

Regional Administrator, Region III U.S. Nuclear Regulatory Commission 801 Warrenville Road Lisle, Illinois 60532-4551

Ms. Lorraine Creek RR 1, Box 182 Manteno, Illinois 60950

Chairman, Ogle County Board Post Office Box 357 Oregon, Illinois 61061

Mrs. Phillip B. Johnson 1907 Stratford Lane Rockford, Illinois 61107 Byron/Braidwood Stations

George L. Edgar Morgan, Lewis and Bochius 1800 M Street, N.W. Washington, DC 20036

Attorney General 500 S. Second Street Springfield, Illinois 62701

Illinois Department of Nuclear Safety Office of Nuclear Facility Safety 1035 Outer Park Drive Springfield, Illinois 62704

Commonwealth Edison Company Byron Station Manager 4450 N. German Church Road Byron, Illinois 61010-9794

Commonwealth Edison Company Site Vice President - Byron 4450 N. German Church Road Byron, Illinois 61010-9794

U.S. Nuclear Regulatory Commission Braidwood Resident Inspectors Office RR 1, Box 79 Braceville, Illinois 60407

Mr. Ron Stephens
Illinois Emergency Services
and Disaster Agency
110 E. Adams Street
Springfield, Illinois 62706

Chairman
Will County Board of Supervisors
Will County Board Courthouse
Joliet, Illinois 60434

Commonwealth Edison Company Braidwood Station Manager RR 1, Box 84 Braceville, Illinois 60407 Ms. Bridget Little Rorem Appleseed Coordinator 117 N. Linden Street Essex, Illinois 60935

Document Control Desk-Licensing Commonwealth Edison Company 1400 Opus Place, Suite 400 Downers Grove, Illinois 60515

Commonwealth Edison Company Site Vice President - Braidwood RR 1, Box 84 Braceville, IL 60407

Mr. David Helwig Senior Vice President Commonwealth Edison Company Executive Towers West III 1400 Opus Place, Suite 900 Downers Grove, IL 60515

Mr. Gene H. Stanley
PWR's Vice President
Commonwealth Edison Company
Executive Towers West III
1400 Opus Place, Suite 900
Downers Grove, IL 60515

Mr. Steve Perry BWR's Vice President Commonwealth Edison Company Executive Towers West III 1400 Opus Place, Suite 900 Downers Grove, IL 60515

Mr. Dennis Farrar
Regulatory Services Manager
Commonwealth Edison Company
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

Ms. Irene Johnson, Licensing Director Nuclear Regulatory Services Commonwealth Edison Company Executive Towers West III 1400 Opus Place, Suite 500 Downers Grove, IL 60515

Commonwealth Edison Company Reg. Assurance Supervisor - Braidwood RR 1, Box 79 Braceville, Illinois 60407

Commonwealth Edison Company Reg. Assurance Supervisor - Byron 4450 N. German Church Road Byron, Illinois 61010-9794

Mr. Michael J. Wallace Senior Vice President Commonwealth Edison Company Executive Towers West III 1400 Opus Place, Suite 900 Downers Grove, IL 60515 Mr. Oliver D. Kingsley, President Nuclear Generation Group Commonwealth Edison Company Executive Towers West III 1400 Opus Place, Suite 500 Downers Grove, IL 60515

SUBJECT: EVALUATION OF COMMONWEALTH EDISON COMPANY RESPONSE TO NRC GENERIC LETTER 97-05 FOR BYRON STATION, UNITS 1 AND 2 AND BRAIDWOOD STATION, UNITS 1 AND 2 (TAC NOS. MA0447, MA0448, MA0449 AND MA0450)

Dear Mr. Kingsley:

On December 17, 1997, the NRC issued Generic Letter (GL) 97-05, "Steam Generator Tube Inspection Techniques." GL 97-05 required a response from licensees which addressed whether it is their practice to leave steam generator tubes with indications in service based on sizing, and if yes, to provide a written report that includes, for each type of indication, a description of the associated nondestructive examination method being used and the technical basis for the acceptability of the technique used. The focus of GL 97-05 was to verify that licensee steam generator tube inspection practices were consistent with existing regulatory requirements and plant licensing bases. By letter dated February 27, 1998, Commonwealth Edison Company submitted a response to this GL that included a description and technical basis for all inspection techniques used to size the depth of steam generator tube degradation at Byron Station, Units 1 and 2, and Braidwood Station, Units 1 and 2. The staff's review of your response did not identify any concerns with the steam generator tube inspection techniques employed at Byron or Braidwood that would indicate noncompliance with the current licensing basis for this facility. This concludes our review of GL 97-05 for Byron Station, Units 1 and 2, and Braidwood Staion, Units 1 and 2.

Sincerely,

John B. Hickman, Project Manager Project Directorate III-2 Division of Reactor Projects - III/IV Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455 STN 50-456 and STN 50-457

cc: See next page

DISTRIBUTION:

Docket File

S. Richards PD3-2 rlk

C. Moore E. Adensam, EGA1

PUBLIC

OGC, O-15B18

P. Rush

M. Jordan, RIII

DOCUMENT NAME: G:\CM\BRAID-BY\BB0449.LTR \*No changes to evaluation memo
To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E"
= Copy with enclosures "N" = No copy

OFFICE	PM:PDIII-2	LA:PDIII-2	PM:PDIII-2	(A)C:EMCB*	D:PDIII-2
NAME	JHickman:sp900	CMoore Ch Lor	SBailey 5.43	ELMurphy	SRichards
DATE	08/26/98	08/ 26/98	08/26 /98	08/04/98	087 / 198

OFFICIAL RECORD COPY

10



## NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

October 9, 1998

Mr. Oliver D. Kingsley, President Nuclear Generation Group Commonwealth Edison Company Executive Towers West III 1400 Opus Place, Suite 500 Downers Grove, IL 60515

SUBJECT: EVALUATION OF COMMONWEALTH EDISON COMPANY RESPONSE TO NRC GENERIC LETTER 97-05 FOR BYRON STATION, UNITS 1 AND 2 AND BRAIDWOOD STATION, UNITS 1 AND 2 (TAC NOS. MA0447, MA0448, MA0449 AND MA0450)

Dear Mr. Kingsley:

On December 17, 1997, the NRC issued Generic Letter (GL) 97-05, "Steam Generator Tube Inspection Techniques." GL 97-05 required a response from licensees which addressed whether it is their practice to leave steam generator tubes with indications in service based on sizing, and if yes, to provide a written report that includes, for each type of indication, a description of the associated nondestructive examination method being used and the technical basis for the acceptability of the technique used. The focus of GL 97-05 was to verify that licensee steam generator tube inspection practices were consistent with existing regulatory requirements and plant licensing bases. By letter dated February 27, 1998, Commonwealth Edison Company submitted a response to this GL that included a description and technical basis for all inspection techniques used to size the depth of steam generator tube degradation at Byron Station, Units 1 and 2, and Braidwood Station, Units 1 and 2. The staff's review of your response did not identify any concerns with the stearn generator tube inspection techniques employed at Byron or Braidwood that would indicate noncompliance with the current licensing basis for these facilities. This concludes our review of GL 97-05 for Byron Station, Units 1 and 2, and Braidwood Station, Units 1 and 2.

Sincerely,

John B. Hickman, Project Manager

le B Hit

Project Directorate III-2

Division of Reactor Projects - III/IV
Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455 STN 50-456 and STN 50-457

cc: See next page