FEB 2 8 10 0

Docket No. 50-334

Duquesne Light Company ATTN: Mr. J. J. Carey Vice President Nuclear Group Post Office Box 4 Shippingport, Pennsylvania 15077

Gentlemen:

Subject: Inspection No. 50-334/85-25

This refers to your letter dated February 11, 1986, in response to our letter dated January 15, 1986.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By: Jacque F. Durr


Stewart D. Ebneter, Director Division of Reactor Safety

cc w/encl:

H. M. Siegel, Manager, Nuclear Engineering Department
C. E. Ewing, QA Manager
W. S. Lacey, Station Superintendent
R. Druga, Chief Engineer
J. Sieber, Manager, Nuclear Safety and Licensing
T. D. Jones, Manager, Nuclear Operations
N. R. Tonet, Manager, Nuclear Engineering
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Pennsylvania

OFFICIAL RECORD COPY

RL BV1 85-25 - 0001.0.0 02/25/86



Duquesne Light Company

bcc w/encl: Region I Docket Room (with concurrences) Management Assistant, DRMA (w/o encl) Section Chief, DRP M. McBride, RI, Pilgrim G. Walton, SRI, BV-2 J. Shapaker, PSB/PWR-A, NRR S. West, PSB/BWR-A, NRR P. Tam, LPM, (Beaver Valley-1), NRR

RI:DRS Pullani/fi 02/24/86 cle for SP

RI:DRS Anderson 02/21/86 RI:DRS Durr 02/27/86

RN:D Ebn 86

OFFICIAL RECORD COPY

RL BV1 85-25 - 0002.0.0 02/25/86



Telephone (412) 393-6000

Nuclear Group P.O. Box 4 Shippingport, PA 15077-0004

February 11, 1986

JU. S. Nuclear Regulatory Commission Office of Inspection & Enforcement Attn: Mr. Stewart D. Ebneter, Director Division of Reactor Safety 631 Park Avenue King of Prussia, PA 19406

Reference: Beaver Valley Power Station, Unit No. 1 Docket No. 50-334, License No. DRP-66 Inspection Report 85-25

Gentlemen:

In response to your letter of January 15, 1986, and in accordance with 10CFR2.201, the attached reply addresses the Notice of Violation which was included with the referenced report.

If you have any questions concerning this response, please contact my office.

Very truly yours,

J. J. Carey Vice President Nuclear Group

Attachment cc: Mr. W. M. Troskoski, Resident Inspector U. S. Nuclear Regulatory Commission Beaver Valley Power Station Shippingport, PA 15077

U. S. Nuclear Regulatory Commission c/o Document Management Branch Washington, DC 20555

Director, Safety Evaluation & Control Virginia Electric & Power Company P. O. Box 26666 One James River Plaza Richmond, VA 23261

Director of Nuclear Reactor Regulation United States Nuclear Regulatory Commission Attn: Mr. Peter S. Tam, Project Manager Project Directorate No. 2 Division of PWR Licensing-A Washington, DC 20555 COMMONWEALTH OF PENNSYLVANIA)

On this the day of <u>lettrey</u>, <u>APC</u>, before me, <u>Muta M. hatter</u>, a Notary Public in and for said Commonwealth and County, personally appeared J. J. Carey, who being duly sworn, deposed, and said that (1) he is Vice President of Duquesne Light, (2) he is duly authorized to execute and file the foregoing Submittal on behalf of said Company, and (3) the statements set forth in the Submittal are true and correct to the best of his knowledge, information and belief.

SS:

Alula m. hastro

SHEILA M. FATTORE, NOTARY PUBLIC SHIPPINGPORT BORO, BEAVER COUNTY MY COMMISSION EXPIRES OCT. 23, 1989 Member, Pennsylvania Association of Notarty

DUQUESNE LIGHT COMPANY Beaver Valley Power Station, Unit No. 1

Reply to Notice of Violation Inspection 85-25 Letter dated January 15, 1986

VIOLATION A (Severity Level IV; Supplement 1)

Description of Violation (85-25-04)

14. 2

10CFR50, Appendix R, Section III.J, requires that emergency lighting units with at least an 8-hour battery power supply shall be provided in all areas needed for operation of safe shutdown equipment and in access and egress routes thereto.

Contrary to the above, as of November 22, 1985, the emergency lighting units with at least an 8-hour battery power supply were not provided in the following safe shutdown access and egress routes:

- 1. Clean Shop (Fire Area SH-1)
- Stairway vestibule immediately outside the Control Room in the Service Building.
- The corridor between the aforementioned stairway (item 2) and the Service Building roof.
- 4. The Service Building roof and the Yard Area between the Service Building and the Diesel Generator Building.

Corrective Steps Taken and Results Achieved

An emergency light has been installed in the clean shop to provide lighting for the access pathway.

An exemption request was submitted on January 21, 1986 requesting an exemption from Section III.J of 10CFR50, Appendix R to allow for the use of security perimeter lighting for areas identified in items 2, 3 and 4 above. The exemption request provides justification to demonstrate that the security lighting capability provides an acceptable margin of safety equivalent to the requirements of Section III.J.

Corrective Steps Taken to Avoid Further Violations

With the installation of an additional emergency light in the clean shop for Item 1 and the exemption request justifying equivalency to the requirements of Section III.J of Appendix R to 10CFR50 for items 2, 3 and 4, no further action is required.

Date When Full Compliance Will Be Achieved

Pending satisfactory acceptance of the exemption request for emergency lighting capability, full compliance will be achieved.