



Northeast
Nuclear Energy

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station
Northeast Nuclear Energy Company
P.O. Box 128
Waterford, CT 06385-0128
(860) 447-1791
Fax (860) 444-4277

The Northeast Utilities System

OCT 13 1998

Docket No. 50-336
B17499

Re: 10 CFR 50.73(a)(2)(ii)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


Millstone Nuclear Power Station, Unit No. 2
Licensee Event Report 98-022-00
Auxiliary Feedwater DC Power Supply Failure
Not Considered in Safety Analysis

This letter forwards Licensee Event Report (LER) 98-022-00, documenting a condition that was discovered at Millstone Nuclear Power Station, Unit No. 2, on September 10, 1998. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(ii).

The commitments made by Northeast Nuclear Energy Company (NNECO) within this letter are included in Attachment 1.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY



J. A. Price
Director - Millstone Unit No. 2

cc: see page 2

9810160095 981013
PDR ADOCK 05000336
S PDR

11
IE 22

Attachments: 1. List of Regulatory Commitments
2. LER 98-022-00

cc: H. J. Miller, Region I Administrator
D. G. McDonald, Jr., NRC Senior Project Manager, Millstone Unit No. 2
S. Dembeck, NRC Project Manager, Millstone Unit No. 1
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2
E. V. Imbro, Director, Millstone ICAVP Inspections

Docket No. 50-336
B17499

Attachment 1
Millstone Nuclear Power Station, Unit No. 2
Commitments

October 1998

Attachment 1

Regulatory Commitment Enclosure
List of Regulatory Commitments

The following table identifies those actions committed to by NNECO in this document.

REGULATORY COMMITMENT	COMMITTED DATE OR OUTAGE
B17499.01: Causal factors to determine the extent of the condition will be identified and appropriate corrective actions taken.	Mode 4 from current outage

Docket No. 50-336
B17499

Attachment 2

Millstone Nuclear Power Station, Unit No. 2

LER 98-022-00

October 1998