

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Shoreham Nuclear Power Station Unit #1		DOCKET NUMBER (2) 0 5 0 0 0 3 2 2	PAGE (3) 1 OF 01
---	--	--------------------------------------	---------------------

TITLE (4)  
Seismic Monitoring Instrumentation inoperable for more than 30 days

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME(S)		DOCKET NUMBER(S)
08	10	88	88	013	00	09	19	88			0 5 0 0 0 0 0 0
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)											

OPERATING MODE (9)	20.402(b)	20.408(e)	90.73(a)(2)(iv)	72.71(b)
POWER LEVEL (10) 0100	20.408(a)(1)(i)	90.36(a)(1)	90.73(a)(2)(v)	72.71(c)
	20.408(a)(1)(ii)	90.36(a)(2)	90.73(a)(2)(vi)	<input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 360A)
	20.408(a)(1)(iii)	90.73(a)(2)(i)	90.73(a)(2)(vii)(A)	Special Report
	20.408(a)(1)(iv)	90.73(a)(2)(ii)	90.73(a)(2)(vii)(B)	
	20.408(a)(1)(v)	90.73(a)(2)(iii)	90.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME Robert W. Grunseich, Operational Compliance Engineer	TELEPHONE NUMBER 5 1 6 9 2 9 - 8 3 0 0
--	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During the performance of SP 44.655.03, Seismic Monitoring Instrumentation Calibration and Functional Test, the following Response Spectrum Recorders were removed from service for calibration: Z94-ZR005CZ (Control Bldg. - el. 44') on 8/10/88, Z94-ZR005CY (Control Bldg. - el. 44') on 8/15/88 and Z94-ZR005BX (Reactor Pedestal - el. 78') on 8/25/88. During calibration, new parts were required. Replacement parts were unavailable. The new parts are expected to be onsite by 9/30/88.

At this time, the relevant portions of SP 44.655.03 will be performed and the recorders returned to service.

8809230274 880919  
PDR ADOCK 05000322  
S PNU

IE 22  
111



**LONG ISLAND LIGHTING COMPANY**

SHOREHAM NUCLEAR POWER STATION • P.O. BOX 628 • WADING RIVER, NEW YORK 11792

TEL. (516) 929-8300

September 19, 1988

PM-38-213

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Dear Sir:

In accordance with Shoreham Nuclear Power Station's Technical Specifications Sections 6.9.2 and 3.3.7.2, enclosed is a Special Report (LER 88-013) on the inoperability of Seismic Monitoring Instrumentation located in the Reactor Building and the Control Building.

Sincerely yours,

William E. Steiger, Jr.  
Plant Manager

MJE/jp

Enclosure

cc: William T. Russell, Regional Administrator  
Frank Crescenzo, Resident Inspector  
Institute of Nuclear Power Operations, Records Center  
American Nuclear Insurers

SR.A21.0200

JE22  
1/1